





report date: 2024-03-29

General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 208 ALLURE EV |
| Colour | Red |
| Year of manufacture | 2020 |
| Top speed | 93 mph |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| Power | 134 BHP |
|-------------|-------------|
| Max. torque | 300 Nm |
| Fuel type | Electricity |



CarCheck.co.uk page 1/10



Internet history

Entry 6

Date 2023-02-13

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 5

Date 2023-01-04

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 4

Date 2023-01-03

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

 Date
 2021-12-16

 Pictures
 0

Listing price <u>View report</u>

source: heycar.co.uk

Entry 2

| Date 2021-10-05 | |
|-----------------|--|

CarCheck.co.uk page 2/10

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

Entry 1

| Date | 2021-10-05 |
|---------------|-------------|
| Pictures | 0 |
| Listing price | View report |

source: heycar.co.uk



MOT history

| MOT expiry date | 2024-07-06 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 1 |
| Failed MOT tests | 0 |
| Total advice items | 2 |
| Total items failed | 0 |

| MOT #1 | | 2023-07-07 07:45 |
|---|---|------------------|
| MOT test | number | 898978411025 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-06 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |


CarCheck.co.uk page 3/10



See MOT history

Tax & MOT check

Full MOT history



CarCheck.co.uk page 4/10



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

| · · | | |
|--|-----------|------|
| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | | GEOT |
| | | |
| | | |
| | | |
| | | |
| ******** | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes See in this check if this PEUGEOT had different number plates. | | |
| | | |
| Number of plates | | , |
| Current registration | UK NE | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |
| | | |

CarCheck.co.uk page 7/10



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2020-09-05 |
| Last registration | 2023-07-07 |
| Complete history | See info |



| Registration #1 | 2020-09-05 | 13 mi |
|-----------------|------------|-----------|
| Registration #2 | | 11.777 es |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |

More info >

CarCheck.co.uk page 9/10



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 84% |
| Pedestrian | 73% |
| Safety systems | 73% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1745 mm |
|---------------------|---------|
| Height | 1460 mm |
| Length | 4055 mm |
| Wheel base | 2540 mm |
| Kerb weight | 1455 kg |
| Max. allowed weight | 1910 kg |

Additional information

| Number of doors | 5 | |
|---------------------------------|-------------|------------|
| Number of seats | 5 | |
| Number of axles | 2 | |
| Engine number Carcheck.co.uk | 5TA30006268 | page 10/10 |