



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 EXECUTIVE
Colour	Blue
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.0 mpg
CO2 emission	239 g/km
CO2 label	L



**MOT history**

<b>MOT expiry date</b>	2024-08-04
<b>MOT pass rate</b>	80 %
<b>MOT passed</b>	16
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	43
<b>Total items failed</b>	7

<b>MOT #20</b>	2023-07-18 12:39
----------------	------------------

<b>MOT test number</b>	820869908262
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Next expiry date</b>	2024-08-04
-------------------------	------------

**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Engine covers, under trays & sill covers are fitted thus not allowing full inspection

**Advice** Front Suspension arms pins / bushes are worn but not resulting in excessive movement

**Advice** Hand brake just met minimum mot requirements / needs adjustment / repair

**Advice** Not able to check 3rd row seat belts as child seats are fitted across

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front subframe area and all the suspension components are corroded / rubbers are perished

**Advice** Rear Suspension arms pins / bushes are worn but not resulting in excessive movement

**Advice** Slight play / knock in the steering rack / front track rod ends

**Advice** Rear subframe area and all the suspension components are corroded / rubbers are perished

**MOT #19**

2022-08-05 13:02

**MOT test number**

520802256956

**Result**

✓ Passed

**Advice** Front headlights only just meets requirements/misty**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18**

2021-07-27 13:14

**MOT test number**

166667342120

**Result**

✓ Passed

**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Play in steering rack inner joint(s)**MOT #17**

2020-07-29 11:17

**MOT test number**

125914923208

**Result**

✓ Passed

**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2020-07-29 09:40

**MOT test number**

832550717466

**Result****✗ Failed****Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**MOT #15**

2019-08-05 13:17

**MOT test number**

580759684404

**Result****✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #14**

2018-05-22 09:13

**MOT test number**

986882163793

**Result****✓ Passed****MOT #13**

2018-05-22 09:13

**MOT test number**

234427602682

**Result****✗ Failed****Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #12** 2017-05-11 16:14**MOT test number** 855729832399**Result** ✓ Passed**MOT #11** 2017-05-11 14:57**MOT test number** 231721234360**Result** ✗ Failed

- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10** 2016-05-12 15:42**MOT test number** 279882187299**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Brake pads getting low
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Headlamp mounting brackets broken but unit is still secure
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Park brake only just met min braking effort of 16% recommend brake service
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2015-04-29 17:05**MOT test number** 317189415146**Result** ✓ Passed

**MOT #8** 2014-11-15 11:23**MOT test number** 395749614358**Result** ✓ Passed**MOT #7** 2014-02-05 14:34**MOT test number** 886296034022**Result** ✓ Passed**Notice** Slight rust on rear discs**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-02-18 15:12**MOT test number** 317139043085**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2012-02-13 12:58**MOT test number** 627664642034**Result** ✓ Passed**MOT #4** 2011-02-12 09:52**MOT test number** 895623641062**Result** ✓ Passed**Notice** Nearside front tyre worn on inside edge**Notice** Offside front tyre worn on inside edge**Notice** Nearside rear tyre worn on outside edge



MOT #3	2010-02-22 14:45
MOT test number	560053650024
Result	✓ Passed

MOT #2	2010-02-22 09:18
MOT test number	703053550042
Result	✗ Failed
<div><div>Notice</div>Front brake discs very worn</div> <div><div>Fail</div>Registration plate lamp not working (1.1.5c)</div> <div><div>Advice</div>Power steering pump has slight seepage from a joint (2.3.3b)</div>	

MOT #1	2008-12-12 10:37
MOT test number	654377748300
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
4 August 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	4 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-12-20
Last registration	2023-07-18
Complete history	<a href="#">See info</a>



Registration #1	2005-12-20	27 mi
Registration #2	2008-12-12	64.431 mi
Registration #3	2010-02-22	99.576 mi
Registration #4	2010-02-22	99.576 mi
Registration #5	2011-02-12	109.997 mi
Registration #6	2012-02-13	116.884 mi
Registration #7	2013-02-18	123.900 mi
Registration #8	2014-02-05	130.428 mi
Registration #9	2014-11-15	134.646 mi
Registration #10	2015-04-29	139.069 mi
Registration #11	2016-05-12	147.832 mi
Registration #12	2016-05-12	151.277 mi
Registration #13	2016-05-12	151.277 mi
Registration #14	2016-05-12	151.277 mi
Registration #15	2016-05-12	151.277 mi
Registration #16	2016-05-12	151.277 mi
Registration #17	2016-05-12	151.277 mi
Registration #18	2016-05-12	151.277 mi
Registration #19	2016-05-12	151.277 mi
Registration #20	2016-05-12	151.277 mi
Registration #21	2016-05-12	151.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Max. allowed weight	2735 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

267835