



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D T180
Colour	Silver
Year of manufacture	2006
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	40.4 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 2


Date	2021-06-29
Pictures	40
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-28
Pictures	40
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-26
MOT pass rate	81 %
MOT passed	17
Failed MOT tests	4
Total advice items	45
Total items failed	8

MOT #21	2023-08-24 16:46
---------	------------------

MOT test number	904722796738
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-26
------------------	------------

- Advice** Offside Front Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))
- Advice** Slight knocking / play in steering column
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened strong advise (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin on limit (1.1.13 (a) (ii))
- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened strong advise (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil strong advise (5.3.2 (b))

**MOT #20**

2022-08-10 11:36

MOT test number

908407700355

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Slight knocking / play in steering column**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #19**

2022-08-10 11:36

MOT test number

409094568553

Result

✗ Failed

Advice Slight knocking / play in steering column**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #18**

2021-08-27 13:05

MOT test number

418254296977

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened offside and nearside (1.1.14 (a) (ii))**Advice** Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))

**MOT #17**

2021-08-27 13:05

MOT test number

528176509755

Result**✗ Failed**

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement offside and nearside (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened offside and nearside (1.1.14 (a) (ii))

Pass with rectification Nearside Front Seat belt buckle not functioning as intended (7.1.2 (d))

MOT #16

2020-10-17 11:06

MOT test number

712826679037

Result**✓ Passed**

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Tyre pressure fault

MOT #15

2020-10-16 08:33

MOT test number

657686646686

Result**✗ Failed**

Fail Electronic stability control warning lamp indicates a fault (7.12 (e))

Fail Offside Rear Anti-roll bar linkage likely to become detached (5.3.3 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Tyre pressure fault

MOT #14

2019-10-01 09:52

MOT test number

603727717783

Result**✓ Passed**

Advice Tpms light on

Advice Nearside brake slightly binding

**MOT #13** 2018-10-17 11:52**MOT test number** 841563693946**Result** ✓ Passed**Advice** Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12** 2018-07-11 11:33**MOT test number** 320472436089**Result** ✓ Passed**Advice** Tyre pressure warning on**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases centre box in poor condition will need replacing soon (6.1.2 (a))**MOT #11** 2017-07-18 08:48**MOT test number** 338664080259**Result** ✓ Passed**MOT #10** 2016-06-22 11:14**MOT test number** 868114388906**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2015-07-10 09:06**MOT test number** 869111395120**Result** ✓ Passed**Notice** Water headder tank cap missing**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2015-02-26 10:50**MOT test number** 278997055071**Result** ✓ Passed

- Notice** Both front wiper blades split
- Notice** Offside front and nearside rear tyres perished
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #7 2014-02-28 15:06**MOT test number** 666169054083**Result** ✓ Passed**MOT #6** 2013-02-12 12:57**MOT test number** 617023843060**Result** ✓ Passed

- Notice** Both front tyres bald on edges

MOT #5 2012-02-22 11:38**MOT test number** 419193052033**Result** ✓ Passed

- Notice** Both front tyres worn on edges

MOT #4 2011-02-03 09:21**MOT test number** 278484831092**Result** ✓ Passed

- Notice** Both front tyres perished

**MOT #3** 2010-01-27 12:08**MOT test number** 530287820098**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage slightly distorted (2.4.G.1)**Notice** Slight damage to nearside rear tyres outer side wall**MOT #2** 2009-01-27 17:20**MOT test number** 260847029086**Result** ✓ Passed**Notice** Screw in offside front tyre**MOT #1** 2009-01-23 15:40**MOT test number** 283123029044**Result** ✗ Failed**Fail** Nearside Front brake disc excessively pitted (3.5.1h)**Fail** Headlamp not in good working order adversely affecting beam image (1.2.4a)**Notice** Screw in offside front tyre**Advice** Offside Front brake disc slightly pitted (3.5.1h)**Fail** Statutory seat belt missing (5.1.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	26 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-01-19
Last registration	2023-08-24
Complete history	See info



Registration #1	2006-01-19	17 mi
Registration #2	2009-01-23	18.065 mi
Registration #3	2009-01-27	18.104 mi
Registration #4	2010-01-27	20.652 mi
Registration #5	2011-02-03	24.333 mi
Registration #6	2012-02-22	27.573 mi
Registration #7	2013-02-12	30.307 mi
Registration #8	2014-02-28	33.783 mi
Registration #9	2015-02-26	38.170 mi
Registration #10	2015-07-10	39.602 mi
Registration #11	2016-06-22	51.111 mi
Registration #12	2017-07-18	63.447 mi
Registration #13	2018-08-01	75.777 mi
Registration #14	2019-08-01	88.107 mi
Registration #15	2020-08-01	100.437 mi
Registration #16	2021-08-01	112.767 mi
Registration #17	2022-08-01	125.097 mi
Registration #18	2023-08-01	137.427 mi
Registration #19	2024-08-01	149.757 mi
Registration #20	2025-08-01	162.087 mi
Registration #21	2026-08-01	174.417 mi
Registration #22	2027-08-01	186.747 mi
Registration #23	2028-08-01	199.077 mi
Registration #24	2029-08-01	211.407 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1595 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0064421