



Mercedes-Benz

M70LHW


report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Red
Year of manufacture	2009
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-05
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	19
Total items failed	2

MOT #17	2024-02-06 16:56
MOT test number	910575104633
Result	✓ Passed
Next expiry date	2025-02-05
Advice	Nearside Fuel Pipe/s corroded
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Torque arm (5.3.4 (a) (i))
Advice	Nearside Brake pipe corroded, covered in grease or other material Front to rear brake pipes (1.1.11 (c))

**MOT #16**

2024-01-18 11:13

MOT test number

938926796221

Result

✗ Failed

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn Cross arm (5.3.4 (a) (i))**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))**MAJOR** Nearside Rear Sub-frame corroded and seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Torque arm (5.3.4 (a) (i))**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Fuel Pipe/s corroded**MOT #15**

2023-01-23 13:28

MOT test number

477355139501

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14**

2022-01-25 08:19

MOT test number

933288725801

Result

✓ Passed



MOT #13	2022-01-21 14:14
MOT test number	328108100975
Result	✗ Failed
MAJOR Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #12	2021-08-19 12:43
MOT test number	219942320619
Result	✓ Passed

MOT #11	2020-09-02 13:34
MOT test number	378226681887
Result	✓ Passed

MOT #10	2019-08-15 10:50
MOT test number	961642105389
Result	✓ Passed

MOT #9	2018-09-04 10:47
MOT test number	640997140651
Result	✓ Passed

MOT #8	2018-09-03 13:36
MOT test number	818403159207
Result	✗ Failed
Advice Offside Rear Lower Coil spring corroded (5.3.1 (b) (i))	
MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #7	2017-09-04 13:42
MOT test number	686848762276
Result	✓ Passed



MOT #6	2016-09-05 15:58
---------------	------------------

MOT test number	482768544949
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-05-06 16:03
---------------	------------------

MOT test number	815166225152
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-10-27 14:30
---------------	------------------

MOT test number	869280804357
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-10-28 14:44
---------------	------------------

MOT test number	275161403337
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-02-15 13:10
---------------	------------------

MOT test number	545106643002
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front wheel bearing has slight play (2.5.A.3c)
---------------	--

MOT #1	2012-01-30 16:09
---------------	------------------

MOT test number	809140432029
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
5 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-02-20
Last registration	2024-02-06
Complete history	See info



Registration #1	2009-02-20	6 mi
Registration #2	2012-01-30	16.560 mi
Registration #3	2013-02-15	21.702 mi
Registration #4	2013-10-28	24.770 mi
Registration #5	2014-10-27	28.335 mi
Registration #6	2015-05-06	30.338 mi
Registration #7	2016-09-05	46.356 mi
Registration #8	2017-09-04	52.585 mi
Registration #9	2018-09-03	56.148 mi
Registration #10	2018-09-04	56.150 mi
Registration #11	2019-05-20	56.277 mi
Registration #12	2019-05-20	56.277 mi
Registration #13	2019-05-20	56.277 mi
Registration #14	2019-05-20	56.277 mi
Registration #15	2019-05-20	56.277 mi
Registration #16	2019-05-20	56.277 mi
Registration #17	2019-05-20	56.277 mi
Registration #18	2019-05-20	56.277 mi
Registration #19	2019-05-20	56.277 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431253706