





report date: 2024-03-29

# General information

Make	FIAT
Model	500 LOUNGE
Colour	Red
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-03-03

Pictures 31

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



report date: 2024-03-29

# MOT history

MOT expiry date	2025-01-11
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	3

MOT #7	2024-01-12 14:35
MOT test number	204426180854
Result	<b>✓</b> Passed
Next expiry date	2025-01-11

MOT #6	2023-07-20 15:00
MOT test number	993255650820
Result	<b>X</b> Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing also has cuts	(5.2.3 (d) (ii))
Fail Exhaust silencer likely to become detached clamp missing (8.1.1 (b) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing also has cuts (5	5.2.3 (d) (ii))
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting (5.3.4 (a) (i))	in excessive movement

MOT #5	2023-03-02 10:03
MOT test number	772620581224
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3 2021-03-01 16:23

MOT test number 749364081701

Result ✓ Passed

MOT #2

MOT test number

394609126860

Result

✓ Passed

MOT #1 2020-03-27 11:45
MOT test number 933261186669

Result × Failed

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Fail Offside Rear Shock absorbers has an excessively worn bush Top bush (5.3.2 (c))

Advice Offside Rear Nail in tyre Inner tread edge.

Advice Nearside Rear Shock absorbers has a slightly worn bush Top bush (5.3.2 (c))

CarCheck.co.uk page 4/11



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	11 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



MK17GGF report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

MK17GGF

report date: 2024-03-29

# For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>. More info >

# Plate changes

See in this check if this FIAT had different number plates.

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-03-31
Last registration	2024-01-12
Complete history	See info



Registration #1	2017-03-31	25 mi
Registration #2	2020-03-27	17.030 mi
Registration #3	2020-03-31	17.072 mi
Registration #4	2021-03-01	22.094 mi
Registration #5		9.772 es
Registration #6		11.777 es
Registration #7		9.77 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



MK17GGF report date: 2024-03-29

Car features

50225	Air condition
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	see crash video



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 11/11