





report date: 2024-03-29

### General information

Make	FORD
Model	RANGER WILDTRAK DCB 4X4
Colour	Black
Year of manufacture	2009
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm
Engine capacity	2.953 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



report date: 2024-03-29

## Internet history

_				_	-
-	n	т	rv	,	

ciitiy 1	
Date	2021-10-14
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



REO9FBO report date: 2024-03-29

**MOT** history

MOT expiry date	2024-10-10
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	41
Total items failed	2

MOT #16		2022 00 22 11.47
MOT test	numher	2023-09-23 11:47 497832476118
Result		✓ Passed
Next expi	ry date	2024-10-10
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Steering box has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
<b>Advice</b> perishing	Nearside Front Outer Tyre worn close to legal limit/worn on edge Slightly of (5.2.3 (e))	damaged/cracking or
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Offside Front Lower Windscreen damaged but not adversely affecting drive	r's view (3.2 (a) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #15	2022-09-12 16:18	8
MOT test	number 793457017469	9
Result	✓ Passed	d
Advice	Steering box has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))	
Advice	Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule Body to axle (1.1.12 (f) (i))	
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))	

MOT #14	2021-10-11 10:05
MOT test number	432627210704
Result	✓ Passed
MOT #13	2020-09-23 10:45
MOT test number	311326854829
Result	✓ Passed

MOT #12		2020-09-23 09:57
MOT test	number	701299483119
Result		🗙 Failed
MAJOR Advice	Front Registration plate does not conform to the specified requirements (0.1 (d)) Engine covers and under trays fitted	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

Advice

Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))

Advice

Unable to fully test rear seat belts

Advice

Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

MOT #10		2019-08-19 13:07
MOT test	number	613821384949
Result		<b>X</b> Failed
MAJOR	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (	b))
Advice	Rear Leaf spring has slight wear in a shackle pin and/or bush (5.3.4 (a) (i))	
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice	Unable to fully test rear seat belts	
MAJOR	Rear Brake pipe excessively corroded two (1.1.11 (c))	
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b)	)

MOT #9		2018-08-29 14:22
MOT test	number	570596360586
Result		✓ Passed
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b)	)
Advice	Steering box has slight free play detected at steering wheel (2.3 (a) (i))	
Advice	Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8		2017-09-01 13:46
<b>MOT</b> test	number	481329877557
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Steering system has slight free play detected at steering wheel (2.2.A.1b)	

MOT #7		2017-09-01 13:46
MOT test number		221557136460
Result		🗙 Failed
Advice Front registrat	on plate deteriorated but not likely to be misread (6.3.1d)	
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)		

MOT #6	2016-08-30 11:11
MOT test number	639439543411
Result	<b>✓</b> Passed
MOT #5	2015-09-03 11:19
MOT test number	943299088855
Result	✓ Passed
MOT #4	2014-04-24 11:42
MOT test number	177844014127
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

Pass with rectification

Offside Registration plate lamp not working (1.1.C.1d)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2012-04-26 12:53

 MOT test number
 787007512159

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

10 October 2024

See MOT history

### Tax & MOT check

**MOT** expiry date

**Full MOT history** 



CarCheck.co.uk page 8/14



report date: 2024-03-29

### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



REO9FBO report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

_	
Owner	hictory
OWITE	HIISLOLY

*		
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		ave?
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



RE09FBO report date: 2024-03-29

### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-28
Last registration	2023-09-23
Complete history	See info



Registration #1	2009-04-28	7 mi
Registration #2	2012-04-26	32.387 mi
Registration #3	2013-04-22	41.102 mi
Registration #4	2014-04-24	48.512 mi
Registration #5	2015-09-03	58.964 mi
Registration #6	2016-08-30	66.348 mi
Registration #7	2017-09-01	72.665 mi
Registration #8	2017-09-01	72.665 mi
Registration #9	2018-08-29	78.739 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	<del>kol</del> ololok
Video	see crash video



### Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	143645

CarCheck.co.uk page 14/14