



report date: 2024-03-28

General information

Make	SUZUKI
Model	ALTO SZ2
Colour	Silver
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	103 g/km
CO2 label	B



**MOT history**

MOT expiry date	2024-09-07
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #13	2023-09-08 11:33
MOT test number	656104013800
Result	✓ Passed
Next expiry date	2024-09-07

MOT #12	2023-09-08 11:26
MOT test number	654468323151
Result	✗ Failed
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #11	2022-03-28 13:07
MOT test number	229641410216
Result	✓ Passed

MOT #10	2022-03-28 13:07
MOT test number	376767586946
Result	✗ Failed
Pass with rectification	Nearside Stop lamp(s) all not working (4.3.1 (a) (iii))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #9** 2021-03-22 12:59**MOT test number** 844928464922**Result** ✓ Passed**MOT #8** 2020-03-13 10:37**MOT test number** 748538511444**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-03-13 14:04**MOT test number** 238373662727**Result** ✓ Passed**MOT #6** 2018-03-14 13:06**MOT test number** 206151209880**Result** ✓ Passed**MOT #5** 2017-03-15 13:28**MOT test number** 545748492785**Result** ✓ Passed**MOT #4** 2016-05-03 12:52**MOT test number** 658580394741**Result** ✓ Passed**Advice** Slight noise from offside front wheel bearing

**MOT #3** 2015-05-12 15:33**MOT test number** 355012335111**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** 165 60 r 14 75 h**Notice** Both the front wipers are slightly smearing the screen**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-05-07 15:26**MOT test number** 229537924443**Result** ✓ Passed**MOT #1** 2014-05-06 15:36**MOT test number** 876066824197**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Rear brake application uneven (3.7.B.2)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
7 September 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	7 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-15
Last registration	2023-09-08
Complete history	See info



Registration #1	2011-03-15	9 mi
Registration #2	2014-05-06	17.395 mi
Registration #3	2014-05-07	17.399 mi
Registration #4	2015-05-12	43.749 mi
Registration #5	2016-05-03	70.156 mi
Registration #6	2017-03-15	86.276 mi
Registration #7	2018-03-14	97.153 mi
Registration #8	2019-03-20	111.277 mi
Registration #9	2019-03-20	111.277 mi
Registration #10	2019-03-20	111.277 mi
Registration #11	2019-03-20	111.277 mi
Registration #12	2019-03-20	111.277 mi
Registration #13	2019-03-20	111.277 mi
Registration #14	2019-03-20	111.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1412346