





### General information

Make	KIA
Model	CERATO LX
Colour	Silver
Year of manufacture	2006
Top speed	107 mph
0 - 60 mph	13.0 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	103 BHP
Max. torque	143 Nm at 4.500 rpm
Engine capacity	1.599 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg
CO2 emission	187 g/km
CO2 label	J





# Internet history

Entry 1	
Date	20
Pictures	11

2021-07-13

11

Listing price

View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-07-12
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #18	2023-07-08 09:42
MOT test number	552948247332
Result	✓ Passed
Next expiry date	2024-07-12

MOT #17	2022-06-14 10:08
MOT test number	550098073760
Result	✓ Passed

MOT #16	2021-07-13 09:59
MOT test number	701643094167
Result	✓ Passed

MOT #15	2020-08-21 16:50
MOT test number	648100505896
Result	✓ Passed
Advice Front Play in steering rack inner joint(s)	



MOT #14		2019-02-19 10:48
MOT test	number	681253987447
Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Both front tyres wearing on edges	

MOT #13	2018-02-07 14:24
MOT test number	712908695388
Result	✓ Passed
Advice Brake fluid dirty	

MOT #12	2018-02-07 09:55
MOT test number	922627394468
Result	🗙 Failed
Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively dama prevents the ingress of dirt (2.4.G.2)   Advice Brake fluid dirty	aged so that it no longer

MOT #11	2017-03-07 15:17
MOT test number	142332769650
Result	✓ Passed

MOT #10	2017-03-07 09:30
MOT test number	603867032182
Result	🗙 Failed
<b>Fail</b> Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
<b>Pass with rectification</b> Offside Headlamp aim too high (1.8)	

LDO6RJO report date: 2024-03-29





MOT #9	2016-03-03 09:48	
MOT test	<b>number</b> 387704463419	
Result	✓ Passed	
Advice	Engine covers fitted restricting testers view	
Advice	Nearside Front Tyre worn close to the legal limit 3mm=1.4mm useable tread left (4.1.E.1)	
Advice	Front Exhaust has a minor leak of exhaust gases flex. does not reach service standards (7.1.2)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Both front tyres worn on edges	
Advice	Offside Front Tyre worn close to the legal limit 3mm=1.4mm useable tread left (4.1.E.1)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #8		2015-03-04 09:16
MOT test	number	109473265092
Result		🗸 Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Cover sills fitted to door sills restricting testers view	

MOT #7		2014-02-13 14:26
MOT test	number	787524344044
Result		✓ Passed
Notice	Power steering hose damp	
Notice	Exhaust corroded	





MOT #6	2014-02-11 14:52
MOT test number	208132444059
Result	🗙 Failed
<b>Fail</b> Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Notice Power steering hose damp	
<b>Fail</b> Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Notice Exhaust corroded	
MOT #5	2013-03-06 11:02
MOT test number	567175263082

Result		✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Power steering ram(s) has slight seepage from a component (2.3.3b)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)	

МОТ #4	2012-02-13 09:28
MOT test number	989114442002
Result	✓ Passed
<b>Notice</b> Near side rear tyre has cuts in ,no cord exposed.	
Notice Off side front wiper blade split	

MOT #3	2011-02-22 09:20
MOT test number	465273451003
Result	✓ Passed





MOT #2		2010-03-01 12:11
MOT test	number	310780960008
Result		✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (	3.5.1i)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened	l (3.5.1i)

MOT #1	2009-03-10 09:27
MOT test number	242979069082
Result	✓ Passed





#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE CO
Category	 Lashe
Туре	
Damage 2	AMPLE
Damaye 2	e e et al
Date	 1.
Category	 AMP
Туре	

#### Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
*******	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-30
Last registration	2023-07-08
Complete history	See info



Registration #1	2006-03-30	18 mi
Registration #2	2009-03-10	17.311 mi
Registration #3	2010-03-01	22.968 mi
Registration #4	2011-02-22	27.769 mi
Registration #5	2012-02-13	32.090 mi
Registration #6	2013-03-06	37.037 mi
Registration #7	2014-02-11	41.727 mi
Registration #8	2014-02-13	41.737 mi
Registration #9	2015-03-04	48.946 mi
Registration #10	2016-03-03	58.124 mi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		01.777 est
Registration #19		
Registration #19		
Registration #20		11.000 es





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1735 mm
Height	1470 mm
Length	4340 mm
Wheel base	2610 mm
Kerb weight	1363 kg
Max. allowed weight	1753 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	G4ED5H02381