





report date: 2024-03-29

### General information

Make	CITROEN
Model	DS5 HDI DSTYLE
Colour	White
Year of manufacture	2015
Top speed	132 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



# Internet history

### Entry 2

Date 2021-07-26

Pictures 7

Listing price <u>View report</u>









source: yesauto.com

### Entry 1

Date	2021-07-14
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/12



\_\_\_\_

MOT history

MOT expiry date	2024-09-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	5

MOT #9	2023-09-02 10:18
MOT test number	234234613226
Result	✓ Passed
Next expiry date	2024-09-01
Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))	

MOT #8	2023-08-08 16:00	
MOT test number	945094516973	
Result	<b>X</b> Failed	
Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))		
Advice Items removed from driver's view prior to test Dash cam		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

CarCheck.co.uk page 3/12



**MOT #7** 

LC15UOU report date: 2024-03-29

2022-08-01 11:40

MOT test number 734090197389

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Numerous deep cuts in tread area. (5.2.3 (d) (i))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush split (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Very close to legal limit (2mm) in center of tire. Also heavily perished and near bald on outer edge. VERY POOR CONDITION!!! (5.2.3 (e))

MOT #6 2021-08-12 10:00

**MOT test number** 517627128254

**Result** 
✓ Passed

**MOT #5** 2020-09-14 07:58

**MOT test number** 179320340797

**Result** ✓ Passed

MOT #4 2019-09-17 11:26

MOT test number 551626207628

MOT #3 2019-06-13 16:08

**MOT test number** 985203113129

Result \rightarrow Passed

**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

MOT #2 2018-05-22 10:05

MOT test number 631016760701

Result \( \sqrt{Passed} \)

**Advice** Nearside Front Tyre worn close to the legal limit 2.6mm (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit 2.6mm 2354518 97y (4.1.E.1)

CarCheck.co.uk page 4/12



**LC15UOU** 

report date: 2024-03-29

MOT #1 2018-05-18 09:40 **MOT test number** 762920544621 Result × Failed **Advice** Nearside Front Tyre worn close to the legal limit 2.6mm (4.1.E.1) Offside Registration plate lamp does not illuminate simultaneously with the position lamps (1.1.C.1a) Fail Fail Offside Front Outer Brake pad(s) less than 1.5 mm thick (3.5.1g) **Advice** Nearside Rear Tyre worn close to the legal limit 2.6mm 2354518 97y (4.1.E.1) Nearside Front Outer Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	1 September 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



**LC15UOU** 

report date: 2024-03-29

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



about of pliates

factor scincol

LC15UOU

report date: 2024-03-29

# For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this CITROEN had different number plates.

More info >



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-29
Last registration	2023-09-02
Complete history	See info



Registration #1	2015-05-29	19 mi
Registration #2	2018-05-18	51.193 mi
Registration #3	2018-05-22	51.224 mi
Registration #4	2019-06-13	63.384 mi
Registration #5	2019-09-17	63.418 mi
Registration #6	2020-09-14	66.938 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		n.m.

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1540 kg
Max. allowed weight	2125 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZD4075854

CarCheck.co.uk page 12/12