



report date: 2024-11-08

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI
Colour	White
Year of manufacture	2016
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-07-24
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-05-22
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	7
Total items failed	7

MOT #9	2024-05-13 07:59
MOT test number	827130673047
Result	✓ Passed
Next expiry date	2025-05-22

MOT #8	2024-05-13 07:59
MOT test number	505524350416
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #7	2023-05-17 12:05
MOT test number	493665503160
Result	✓ Passed



MOT #6 2023-05-16 11:49

MOT test number 317933934268

Result ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Front Macpherson strut pin or bush worn but not resulting in excessive movement rough when rotated (5.3.4 (a) (i))

MOT #5 2022-05-23 12:17

MOT test number 578569176839

Result ✓ Passed

- Advice** Nearside Front Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))

MOT #4 2021-07-26 09:18

MOT test number 617774308326

Result ✓ Passed

- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3 2020-08-10 15:35

MOT test number 362755037602

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2 2020-08-10 09:54

MOT test number 834204732771

Result ✗ Failed

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-07-26 08:13

MOT test number 897766816316

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2025

✓
MOT

Expires:
22 May 2025

Tax status Valid until 1 August

Days left 235

MOT expiry date 22 May 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-01
Last registration	2024-05-13
Complete history	See info



Registration #1	2016-09-01	27 mi
Registration #2	2019-07-26	28.349 mi
Registration #3	2020-08-10	39.640 mi
Registration #4	2020-08-10	39.641 mi
Registration #5	2021-07-26	49.016 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Wheel base	2750 mm
Kerb weight	1270 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	263A20006186483 LN9