



report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | BMW |
| Model | X5 XDRIVE30D M SPORT |
| Colour | Grey |
| Year of manufacture | 2015 |
| Top speed | 145 mph |
| Gearbox | 8 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 255 BHP |
| Max. torque | 560 Nm at 1.500 rpm |
| Engine capacity | 2.993 cc |
| Cylinders | 6 |
| Fuel type | Diesel |
| Consumption city | 43.5 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-26 |
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 15 |
| Total items failed | 2 |

| | |
|------------------|--|
| MOT #8 | 2023-09-27 10:22 |
| MOT test number | 620330788469 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-26 |
| Advice | Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |
| Advice | Offside Rear Inner Tyre worn close to legal limit/worn on edge SIDE (5.2.3 (e)) |
| Advice | Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #7 | 2022-09-15 10:57 |
| MOT test number | 704360025683 |
| Result | ✓ Passed |
| Advice | Nearside Front knocking from front but nothing found |
| Advice | All tyre sidewalls |

| | |
|-----------------|------------------|
| MOT #6 | 2021-02-01 16:29 |
| MOT test number | 794603977466 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #5 | 2020-01-30 10:33 |
| MOT test number | 483805172631 |
| Result | ✓ Passed |

**MOT #4** 2019-10-03 10:53**MOT test number** 693826948007**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #3** 2019-10-03 10:53**MOT test number** 903808104513**Result** ✗ Failed**Pass with rectification** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**MOT #2** 2018-09-13 13:59**MOT test number** 592382633216**Result** ✓ Passed**Advice** Wipers now smearing.**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1** 2018-09-03 14:53**MOT test number** 449925566459**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Nail in tyre**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Wipers now smearing.



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
26 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 26 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this BMW had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 10 |
| First mileage registration | 2015-09-14 |
| Last registration | 2023-09-27 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2015-09-14 | 25 mi |
| Registration #2 | 2018-09-03 | 78.630 mi |
| Registration #3 | 2018-09-13 | 78.944 mi |
| Registration #4 | 2019-10-03 | 103.355 mi |
| Registration #5 | 2019-10-03 | 103.355 mi |
| Registration #6 | 2019-10-03 | 103.355 mi |
| Registration #7 | 2019-10-03 | 103.355 mi |
| Registration #8 | 2019-10-03 | 103.355 mi |
| Registration #9 | 2019-10-03 | 103.355 mi |
| Registration #10 | 2019-10-03 | 103.355 mi |

More info >



Car features

The BMW factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1881 mm |
| Height | 1624 mm |
| Length | 4671 mm |
| Wheel base | 2810 mm |
| Kerb weight | 1820 kg |
| Max. allowed weight | 2410 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 67 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|----------|
| Number of axles | 2 |
| Engine number | 73619273 |