




report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI CC DSG
Colour	Grey
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	8.1 mpg
Consumption extra urban	5.1 mpg
Consumption combined	6.2 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-10
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-25
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	19
Total items failed	4

MOT #17 2023-11-02 11:57

MOT test number 247836456308

Result ✓ Passed

Next expiry date 2024-11-25

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Central Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive surface corrosion (5.3.6 (a) (i))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MOT #16 2022-11-26 12:41

MOT test number 264641002939

Result ✓ Passed**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15** 2021-11-08 16:09**MOT test number** 519144287232**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #14** 2020-11-04 11:56**MOT test number** 438405963954**Result** ✓ Passed**MOT #13** 2019-11-06 17:59**MOT test number** 488424463946**Result** ✓ Passed**MOT #12** 2018-10-18 11:58**MOT test number** 910458790175**Result** ✓ Passed**MOT #11** 2017-10-06 09:25**MOT test number** 124180417673**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both side (4.1.E.1)**MOT #10** 2016-11-04 16:20**MOT test number** 964683180931**Result** ✓ Passed

**MOT #9** 2016-05-19 16:39**MOT test number** 122272411736**Result** ✓ Passed**MOT #8** 2016-04-14 11:48**MOT test number** 443826216587**Result** ✗ Failed**Advice** Top up oil**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Both rear tyres worn inside edges**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #7** 2015-08-26 16:55**MOT test number** 299598735249**Result** ✓ Passed**MOT #6** 2015-06-01 14:01**MOT test number** 545302455155**Result** ✓ Passed

**MOT #5** 2015-06-01 10:04**MOT test number** 177532755136**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-06-27 15:26**MOT test number** 215128074477**Result** ✓ Passed**MOT #3** 2014-04-29 12:36**MOT test number** 626249814109**Result** ✓ Passed**MOT #2** 2013-02-28 10:32**MOT test number** 836449153021**Result** ✓ Passed**MOT #1** 2011-12-19 16:46**MOT test number** 685073751356**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 November 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	25 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CV58LJE
Plate since	2024-03-29
Current registration	 CV58LJE
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-09-01
Last registration	2023-11-02
Complete history	See info



Registration #1	2008-09-01	24 mi
Registration #2	2011-12-19	14.811 mi
Registration #3	2013-02-28	23.634 mi
Registration #4	2014-04-29	29.996 mi
Registration #5	2014-06-27	30.374 mi
Registration #6	2015-06-01	43.124 mi
Registration #7	2015-06-01	43.124 mi
Registration #8	2015-08-26	45.636 mi
Registration #9	2016-04-14	55.612 mi
Registration #10	2016-05-19	55.664 mi
Registration #11	2016-06-20	55.664 mi
Registration #12	2016-07-20	55.664 mi
Registration #13	2016-08-20	55.664 mi
Registration #14	2016-09-20	55.664 mi
Registration #15	2016-10-20	55.664 mi
Registration #16	2016-11-20	55.664 mi
Registration #17	2016-12-20	55.664 mi
Registration #18	2017-01-20	55.664 mi
Registration #19	2017-02-20	55.664 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1855 mm
Height	1417 mm
Length	4799 mm
Wheel base	2708 mm
Kerb weight	1485 kg
Max. allowed weight	1980 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	4
Number of axles	2
Engine number	CBA 129434