



JDO2WAX

report date: 2024-03-28

General information

Make	LEXUS
Model	IS200 200 SE
Colour	Beige
Year of manufacture	2002
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	153 BHP
Max. torque	195 Nm at 4.600 rpm
Engine capacity	1.988 cc
Cylinders	6
Fuel type	Petrol
Consumption city	21.1 mpg
Consumption extra urban	37.7 mpg
Consumption combined	29.1 mpg
CO2 emission	239 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-06-06
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	27
Total items failed	11

MOT #23	2023-09-27 10:10
MOT test number	722463048741
Result	✓ Passed
Next expiry date	2024-10-06

MOT #22	2023-09-27 10:10
MOT test number	269539071547
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))

MOT #21	2022-10-04 10:44
MOT test number	966975544263
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2022-10-03 11:29**MOT test number** 553715805018**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Fail** Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2021-10-04 09:35**MOT test number** 939303920082**Result** ✓ Passed**MOT #18** 2020-09-29 14:11**MOT test number** 329063404126**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Engine covers and under trays fitted**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #17**

2019-10-01 14:49

MOT test number

344689880103

Result

✓ Passed

Advice

Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2018-09-17 14:26

MOT test number

171475941362

Result

✓ Passed

Advice

Rear sub-frame corroded

MOT #15

2017-09-19 16:15

MOT test number

210988534059

Result

✓ Passed

Advice

Offside Front Inner tyre edge worn

MOT #14

2016-09-26 13:20

MOT test number

703651383497

Result

✓ Passed

Advice

Rear exhaust corroded

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Wipers in poor condition

**MOT #13**

2016-09-15 14:08

MOT test number

534027314676

Result**✗ Failed****Fail** Offside Front Mechanical brake component has restricted free movement (3.5.1k)**Advice** Wipers in poor condition**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Rear exhaust corroded**MOT #12**

2015-09-30 15:36

MOT test number

132586370407

Result**✓ Passed****Advice** Rear anti roll bar rusty**MOT #11**

2015-09-29 09:12

MOT test number

642783641001

Result**✗ Failed****Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear anti roll bar rusty**Fail** Offside rear brake excessively fluctuating (3.7.B.3)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front brake binding**Fail** Rear parking (secondary) brake grabbing severely (3.7.B.6b)**MOT #10**

2014-10-06 14:24

MOT test number

525219574222

Result**✓ Passed****Notice** N/s/front and n/ s/ rear tyres walls cut

**MOT #9** 2013-09-11 16:04**MOT test number** 428174053280**Result** ✓ Passed**MOT #8** 2012-10-03 10:39**MOT test number** 155497672211**Result** ✓ Passed**Notice** Both front tyres wearing slightly on edges also cracking between tread**MOT #7** 2011-09-16 14:23**MOT test number** 396329751429**Result** ✓ Passed**Notice** Both front tyres wearing on edges and tread is starting to crack and perish**MOT #6** 2010-10-07 10:08**MOT test number** 291720880298**Result** ✓ Passed**Notice** Both front tyres have cracks in centre tread**MOT #5** 2009-09-18 14:08**MOT test number** 342901069213**Result** ✓ Passed**Notice** Nearside front tyre has cut in sidewall but not to core**MOT #4** 2008-10-01 12:41**MOT test number** 434255378270**Result** ✓ Passed



MOT #3	2007-09-25 09:53
MOT test number	690568267274
Result	✓ Passed
MOT #2	2006-09-26 08:53
MOT test number	121909066275
Result	✓ Passed
MOT #1	2006-09-26 08:53
MOT test number	302029666499
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper blade deteriorated (8.2.2)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-09-27
Last registration	2023-09-27
Complete history	See info



Registration #1	2002-09-27	25 mi
Registration #2	2006-09-26	17.706 mi
Registration #3	2007-09-25	19.895 mi
Registration #4	2008-10-01	23.999 mi
Registration #5	2009-09-18	26.596 mi
Registration #6	2010-10-07	29.058 mi
Registration #7	2011-09-16	30.921 mi
Registration #8	2012-10-03	33.065 mi
Registration #9	2013-09-11	34.886 mi
Registration #10	2014-10-06	42.357 mi
Registration #11	2015-09-29	44.007 mi
Registration #12	2015-09-30	44.007 mi
Registration #13	2016-09-29	45.377 mi
Registration #14	2017-09-29	46.747 mi
Registration #15	2018-09-29	48.117 mi
Registration #16	2019-09-29	49.487 mi
Registration #17	2020-09-29	50.857 mi
Registration #18	2021-09-29	52.227 mi
Registration #19	2022-09-29	53.597 mi
Registration #20	2023-09-29	54.967 mi
Registration #21	2024-09-29	56.337 mi
Registration #22	2025-09-29	57.707 mi
Registration #23	2026-09-29	59.077 mi
Registration #24	2027-09-29	60.447 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1920 mm
Height	1420 mm
Length	4400 mm
Wheel base	2670 mm
Kerb weight	1285 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	1G6958107