



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH (70BHP)
Colour	Silver
Year of manufacture	2009
Top speed	102 mph
0 - 60 mph	15.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	155 Nm at 1.600 rpm
Engine capacity	1.422 cc
Cylinders	3
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-06-23
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	10
Total items failed	7

MOT #12 2021-06-24 11:52

MOT test number 723679914017

Result ✓ Passed

Next expiry date 2022-06-23

- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2021-06-23 15:52

MOT test number 472468904116

Result ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #10** 2019-06-04 14:01**MOT test number** 376993512225**Result** ✓ Passed

Minor Nearside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9 2019-06-04 14:01**MOT test number** 567848155311**Result** ✗ Failed

Minor Nearside Front Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #8 2018-05-08 17:11**MOT test number** 499520946330**Result** ✓ Passed**MOT #7** 2017-06-07 09:08**MOT test number** 585445381795**Result** ✓ Passed

Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #6 2015-07-09 11:35**MOT test number** 157770295144**Result** ✓ Passed**MOT #5** 2014-07-23 11:05**MOT test number** 127224004231**Result** ✓ Passed

**MOT #4** 2014-07-22 13:20**MOT test number** 256933504290**Result** ✗ Failed

- Fail** Offside Registration plate lamp not fitted (1.1.C.1b)
- Fail** Nearside Steering arm has relative movement at its fixings (2.2.B.1h)
- Fail** Nearside Steering rack gaiter insecure (2.2.D.2d)

MOT #3 2013-07-09 17:07**MOT test number** 767800293198**Result** ✓ Passed**MOT #2** 2013-07-09 09:44**MOT test number** 385640693145**Result** ✗ Failed

- Fail** Nearside Steering arm has relative movement at its fixings (2.2.B.1h)

MOT #1 2012-07-11 10:09**MOT test number** 427263992105**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
13 February 2023

✕
MOT

Expired:
23 June 2022

Tax status	Expired at 13 February 2023
Days left	440 days too late
MOT expiry date	23 June 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CA09XKM
Plate since	2019-06-29
Current registration	 CA09XKM
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-08-03
Last registration	2021-06-24
Complete history	See info



Registration #1	2009-08-03	24 mi
Registration #2	2012-07-11	59.998 mi
Registration #3	2013-07-09	73.377 mi
Registration #4	2013-07-09	73.377 mi
Registration #5	2014-07-22	88.791 mi
Registration #6	2014-07-23	88.792 mi
Registration #7	2015-07-09	97.559 mi
Registration #8	2016-06-29	101.377 mi
Registration #9	2017-06-29	101.377 mi
Registration #10	2018-06-29	101.377 mi
Registration #11	2019-06-29	101.377 mi
Registration #12	2020-06-29	101.377 mi
Registration #13	2021-06-24	101.377 mi
Registration #14	2021-06-24	101.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

BNM309749