





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Silver
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	330 Nm at 1.800 rpm
Engine capacity	1.988 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 2

Date 2021-07-14

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-13	
-----------------	--

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2024-09-15
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	56
Total items failed	10

MOT #18		2023-09-08 14:28
MOT test	number	933634990444
Result		✓ Passed
Next expi	ry date	2024-09-15
Advice	Oil leak on engine	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #17	2022-09-15 15:20
MOT test number	286223072392
Result	✓ Passed

MOT #16 2022-09-12 14:45

MOT test number 966450553609

Result X Failed

Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))

Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))

CarCheck.co.uk page 3/16



report date: 2024-03-28

MOT #15		2021-09-16 16:02
MOT test	number	893553512207
Result		✓ Passed
Advice	Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5	.3.4 (a) (i))
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive	ve movement (5.3.4

MOT #14		2020-10-23 08:37
MOT test	number	380515976688
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both side	es (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice	Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both side	es (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))	

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #13 2020-10-23 08:37

MOT test number 824165213479

Result **X** Failed **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii)) Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Advice Rear Coil spring corroded both sides (5.3.1 (b) (i)) Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/16



Advice

(a) (i))

BK08ETZ

report date: 2024-03-28

MOT #12 2019-04-30 11:17

MOT test number 665482207127 ✓ Passed Result **Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Covers fitted Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) **Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

CarCheck.co.uk page 6/16



MOT #11 2019-04-18 08:38

MOT test number 737165473904

Result X Failed

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a))

Fail Offside Front Road wheel badly distorted (5.2.2 (c) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Covers fitted

Advice Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #10 2018-04-06 08:49

MOT test number 873021996366

Result

Passed

Advice Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear Anti-roll bar has slight play in a pin/bush d bushes (2.4.G.2)

Advice Oil leak

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Wipers slightly smear screen

CarCheck.co.uk page 7/16



MOT #9 2017-03-24 12:55

MOT test number 232681830739

Result ✓ Passed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened innerface (3.5.1i)

Advice Nearside Front tyre sidewall slightly damaged

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened innerface (3.5.1i)

Advice Rear brake pads worn

MOT #8 2017-03-20 11:46

MOT test number 419512944472

Result X Failed

Fail Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

Advice Nearside Front tyre sidewall slightly damaged

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened innerface (3.5.1i)

Fail Nearside Front Tyre has ply or cords exposed sidewall (4.1.D.1b)

Advice Rear brake pads worn

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened innerface (3.5.1i)

MOT #7 2016-02-01 09:16

MOT test number 667973923589

Result

Very Passed

MOT #6 2015-01-16 14:30

MOT test number 515036215084

Result
✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #5 2015-01-16 09:24

MOT test number 425856815039

Result × Failed

Fail Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #4 2014-02-10 17:12

MOT test number 677611544052

Result \rightarrow Passed

MOT #3 2013-02-05 11:19

MOT test number 995966933078

Result
✓ Passed

MOT #2 2012-02-07 14:06

MOT test number 665858432032

Result ✓ Passed

MOT #1 2011-02-22 10:30

MOT test number 118763351047

Result \rightarrow Passed

Notice Wet test + pans

CarCheck.co.uk page 9/16



Tax & MOT check





Expires: 15 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	15 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 10/16



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK UK
Flate since	
Current registration	NIK NIK
Plate since	

CarCheck.co.uk page 13/16



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 14/16



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-26
Last registration	2023-09-08
Complete history	See info



Registration #1	2008-03-26	15 mi
Registration #2	2011-02-22	55.428 mi
Registration #3	2012-02-07	63.693 mi
Registration #4	2013-02-05	66.560 mi
Registration #5	2014-02-10	70.052 mi
Registration #6	2015-01-16	74.263 mi
Registration #7	2016-02-01	81.943 mi
Registration #8	2017-03-20	87.504 mi
Registration #9	2017-03-24	87.523 mi
		02.006!
Registration #10	2018-04-06	92.996 mi
Registration #10 Registration #11	2018-04-06	92.996 mi
		92.996 MI
Registration #11		92.996 MI
Registration #11 Registration #12		92.996 MI
Registration #11 Registration #12 Registration #13		92.996 MI
Registration #11 Registration #12 Registration #13 Registration #14		92.996 MI
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		92.996 MI
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		92.996 MI
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		92.996 MI

More info >

CarCheck.co.uk page 15/16



Safety ratings

				TA.	
--	--	--	--	-----	--

Video <u>see crash video</u>



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0806030302416G

CarCheck.co.uk page 16/16