





General information

Make	CITROEN
Model	DS3 DSTYLE BY BENEFIT
Colour	White
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1		
Date	2021-01-29	
Pictures	10	
Listing price	View report	









source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	15
Total items failed	1

MOT #7		2024-02-09 13:42
MOT test i	number	457947472007
Result		✓ Passed
Next expiry date 2025-02-2		2025-02-26
Advice	Offside Front Tyre worn close to legal limit/worn on edge bald inner edge	(5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge bald on inner e	edge (5.2.3 (e))

MOT #6		2023-02-10 14:06
MOT test	number	772647940565
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))

MOT #5	2022-02-25 13:03	8
MOT test	number 758320172210)
Result	✓ Passed	ł
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Fluid leak, but not excessive Coolant leaking from coolant reservoir as cracked (8.4.1 (a) (i))		





MOT #4	2022-02-25 12:03	
MOT test number	349448948654	
Result	× Failed	
Advice Rear Tyre slightly dama	ged/cracking or perishing Both (5.2.3 (d) (ii))	
Advice Fluid leak, but not exces	ssive Coolant leaking from coolant reservoir as cracked (8.4.1 (a) (i))	
Advice Nearside Rear Nail in ty	re	
Advice Nearside Rear Tyre work	n close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice Front Brake pad(s) wear	ing thin (1.1.13 (a) (ii))	

MOT #3	2021-02-27 18:49
MOT test number	181595687132
Result	✓ Passed

MOT #2		2019-05-04 09:00
MOT test	number	217333165331
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust support bracket corroded [Before silencer]	

MOT #1	2018-05-16 08:19
MOT test number	757617886139
Result	✓ Passed



Tax & MOT check

Tax due:	MOT Expires:
1 May 2025	26 [°] February 2025
Tax status	Valid until 1 May
Days left	366
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

4
AMP
- A

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-05-16
Last registration	2024-02-09
Complete history	<u>See info</u>



Registration #1	2015-05-16	24 mi
Registration #2	2018-05-16	21.104 mi
Registration #3	2019-05-04	28.805 mi
Registration #4		11.777 esi
Registration #5	2021-02-27	40.749 mi
Registration #6		11.777 esi
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		10.200 mi

More info >





Safety ratings

NCAP rating	****
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight	
Width	1708 mm
Height	1460 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1575 kg
Additional information	
Additional information Fuel tank capacity	48
	48 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 3