





report date: 2024-03-29

General information

Make	PEUGEOT	
Model	PARTNER BLUE HDI S L1	
Colour	White	
Year of manufacture	2017	
Top speed	98 mph	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2022-06-17

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-25	
Pictures	2	
Listing price	View report	





source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-26
MOT pass rate	57 %
MOT pass rate	31 //
MOT passed	4
Failed MOT tests	3
Total advice items	11
Total items failed	6

MOT #7		2023-07-27 13:01
MOT test num	nber	849603886387
Result		✓ Passed
Next expiry o	late	2024-07-26
Advice Fr	ont Oil leak, but not excessive (8.4.1 (a) (i))	
Advice No	earside Front Child Seat fitted not allowing full inspection of adult belt	
Advice Ne	earside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Of	fside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6		2023-07-27 13:01
MOT test number		566674191539
Result		× Failed
Advice Nearside Front (Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))		
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Front (Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

CarCheck.co.uk page 3/11



NV17YPE

report date: 2024-03-29

MOT #5 2022-06-11 10:35
MOT test number 371345406685

Result ✓ Passed

MOT #4 2022-06-07 14:37

MOT test number 311342546492

Result X Failed

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #3 2021-04-27 09:29

MOT test number 493909893547

Result ✓ Passed

MOT #2 2021-04-26 14:46

MOT test number 672425475646

Result X Failed

Pass with rectification Nearside Front Headlamp aim too high adjusted during test (4.1.2 (a))

Fail Front Windscreen washer provides insufficient washer liquid washer bottle full (3.5 (a))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Pass with rectification Offside Front Headlamp aim too high adjusted during test (4.1.2 (a))

MOT #1 2020-06-30 12:59

MOT test number 738675000244

Result ✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	OK SIZ
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-07-17
Last registration	2023-07-27
Complete history	See info



Registration #1	2017-07-17	14 mi
Registration #2	2020-06-30	61.330 mi
Registration #3	2021-04-26	73.327 mi
Registration #4	2021-04-27	73.328 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

D: 1000	ensior	~ ~ C		ьь
		15 ~	\mathbf{w}	

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1292 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBHB0040320

CarCheck.co.uk page 11/11