



NA60FZS

report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



## MOT history

MOT expiry date	2025-04-04
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	43
Total items failed	9

MOT #16 2024-04-05 14:23

MOT test number 900988759788

Result ✓ Passed

Next expiry date 2025-04-04

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15 2023-01-11 10:25

MOT test number 378779717633

Result ✓ Passed

MOT #14 2022-01-10 14:33

MOT test number 158300585591

Result ✓ Passed

**MOT #13**

2020-10-27 09:03

**MOT test number**

838777225782

**Result**

✓ Passed

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust silencer corroded
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12**

2020-10-26 10:09

**MOT test number**

373535709608

**Result**

✗ Failed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Offside Front Coil spring fractured or broken top of spring (5.3.1 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Front Coil spring fractured or broken top of spring (5.3.1 (b) (i))
- Advice** Exhaust silencer corroded
- MAJOR** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #11**

2019-11-01 10:49

**MOT test number**

901684797807

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Outer skin on exhaust back box deteriorated
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10**

2019-10-31 09:08

**MOT test number**

887082889200

**Result**

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Outer skin on exhaust back box deteriorated
- MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #9**

2018-10-26 14:06

**MOT test number**

769989403612

**Result**

✓ Passed

- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both wishbone rear bushes (5.3.4 (a) (i))

**MOT #8** 2018-10-25 14:43**MOT test number** 642289093081**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both wishbone rear bushes (5.3.4 (a) (i))**MOT #7** 2017-10-04 10:30**MOT test number** 695162924710**Result** ✓ Passed**MOT #6** 2016-10-03 10:14**MOT test number** 717466744372**Result** ✓ Passed**Advice** Front part of n/s front inner wing guard loose**Advice** Offside Seat belt stitching slightly frayed (5.2.2b)**Advice** Vehicle type dropside truck**Advice** Engine oil level low [not showing on dipstick]**Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides at rear bushes (2.4.G.2)**MOT #5** 2015-10-30 09:21**MOT test number** 239136094436**Result** ✓ Passed**Advice** Vehicle body dropside truck**MOT #4** 2014-10-18 09:02**MOT test number** 819031794260**Result** ✓ Passed

**MOT #3** 2014-10-14 17:33**MOT test number** 199667784298**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
- Fail** Rear fog lamp not working (1.3.2b)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #2** 2013-10-28 12:19**MOT test number** 545041603330**Result** ✓ Passed

- Notice** O/s side repeater in mirror lense cracked

**MOT #1** 2013-10-25 14:14**MOT test number** 339248193217**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Notice** O/s side repeater in mirror lense cracked
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-27
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2010-10-27	12 mi
Registration #2	2013-10-25	34.278 mi
Registration #3	2013-10-28	34.280 mi
Registration #4	2014-10-14	48.508 mi
Registration #5	2014-10-18	48.508 mi
Registration #6	2015-10-30	50.874 mi
Registration #7	2016-10-03	57.944 mi
Registration #8	2017-10-04	63.898 mi
Registration #9	2018-10-25	75.943 mi
Registration #10	2019-10-27	88.997 mi
Registration #11	2019-10-27	88.997 mi
Registration #12	2019-10-27	88.997 mi
Registration #13	2019-10-27	88.997 mi
Registration #14	2019-10-27	88.997 mi
Registration #15	2019-10-27	88.997 mi
Registration #16	2019-10-27	88.997 mi
Registration #17	2019-10-27	88.997 mi

More info >



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2015 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20411973