





report date: 2024-03-29

General information

| Make | MINI | |
|---------------------|----------------|--|
| Model | CLUBMAN COOPER | |
| Colour | Silver | |
| Year of manufacture | 2017 | |
| Top speed | 129 mph | |
| 0 - 60 mph | 8.8 seconds | |
| Gearbox | 6 speed Manual | |

Engine & fuel consumption

| Power | 134 BHP | |
|-------------------------|---------------------|--|
| Max. torque | 220 Nm at 4.200 rpm | |
| Engine capacity | 1.499 сс | |
| Cylinders | 3 | |
| Fuel type | Petrol | |
| Consumption city | 44.8 mpg | |
| Consumption extra urban | 62.8 mpg | |
| Consumption combined | 54.3 mpg | |
| CO2 emission | 118 g/km | |
| CO2 label | С | |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-12

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



BM17KMX report date: 2024-03-29

MOT history

| MOT expiry date | 2025-02-06 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 5 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| MOT #5 | | 2024-01-18 10:02 |
|-----------|--|------------------|
| MOT test | number | 794634308723 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-02-06 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Nail in tyre | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| MOT #4 | 2023-01-24 11:13 |
|---|------------------|
| MOT test number | 918526878916 |
| Result | ✓ Passed |
| Advice Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) | |

| MOT #3 | 2022-02-07 10:17 |
|-----------------|------------------|
| MOT test number | 101341637237 |
| Result | ✓ Passed |
| | |

| MOT #2 | 2020-07-30 13:56 |
|-----------------|------------------|
| MOT test number | 729657786551 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #1

MOT test number

443619834686

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 6 February 2025 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

BM17KMX

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-07-31 |
| Last registration | 2024-01-18 |
| Complete history | See info |



| Registration #1 | 2017-07-31 | 19 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-07-30 | 22.633 mi |
| Registration #3 | | 11,777 mi |
| Registration #4 | | 71,777 es |
| Registration #5 | | 71,777 66 |
| Registration #6 | | D.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 79% |
| Children | 73% |
| Pedestrian | 66% |
| Safety systems | 56% |
| Overall rating | 71% |
| Video | see crash video |



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1415 mm |
| Length | 3821 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1280 kg |
| Max. allowed weight | 1670 kg |

Additional information

| Fuel tank capacity | 40 | |
|-----------------------------------|------------------|-----------|
| Fuel delivery | Direct Injection | |
| Number of doors | 2 | |
| Number of seats CarCheck.co.uk | 4 pa | age 11/11 |