



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR SPECIAL EDITION
Colour	Silver
Year of manufacture	2004
Top speed	147 mph
0 - 60 mph	7.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-27
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-05-05
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	21
Total items failed	11

MOT #21	2022-04-28 16:02
MOT test number	762728499084
Result	✓ Passed
Next expiry date	2023-05-05
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #20	2022-04-28 10:49
MOT test number	405653037951
Result	✗ Failed
Fail	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Steering damper defective
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MOT #19	2021-05-06 08:42
MOT test number	283265293792
Result	✓ Passed

**MOT #18** 2021-04-22 13:25**MOT test number** 310979440360**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**MOT #17** 2020-10-22 09:46**MOT test number** 975289661399**Result** ✓ Passed**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #16** 2020-10-22 09:46**MOT test number** 863144214115**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #15** 2019-05-03 12:56**MOT test number** 403412341811**Result** ✓ Passed**MOT #14** 2019-04-29 09:48**MOT test number** 131583083725**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13**

2018-05-08 08:38

MOT test number

771625503077

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front tyre worn on inner edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12**

2017-04-13 09:54

MOT test number

484395336708

Result

✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Both front tyres slightly worn on edge**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11**

2016-04-18 10:10

MOT test number

230381816972

Result

✓ Passed

MOT #10

2015-05-05 09:37

MOT test number

995785625174

Result

✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Engine management light illuminated



MOT #9	2014-05-09 09:39
---------------	------------------

MOT test number	208589224114
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)
---------------	--

Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

MOT #8	2013-05-08 11:33
---------------	------------------

MOT test number	547978123154
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2012-05-09 09:28
---------------	------------------

MOT test number	888940632116
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2011-05-12 12:09
---------------	------------------

MOT test number	678282931114
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-05-10 11:37
---------------	------------------

MOT test number	801120030148
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-05-13 16:03
---------------	------------------

MOT test number	164683939122
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #3	2009-05-12 09:30
MOT test number	794952639181
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2008-05-07 10:53
MOT test number	444601113165
Result	✓ Passed

MOT #1	2007-05-02 09:43
MOT test number	453692127146
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
23 July 2022

✕
MOT

Expired:
5 May 2023

Tax status	Expired at 23 July 2022
Days left	646 days too late
MOT expiry date	5 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-05-12
Last registration	2022-04-28
Complete history	See info



Registration #1	2004-05-12	19 mi
Registration #2	2007-05-02	14.818 mi
Registration #3	2008-05-07	19.331 mi
Registration #4	2009-05-12	22.821 mi
Registration #5	2009-05-13	22.826 mi
Registration #6	2010-05-10	26.307 mi
Registration #7	2011-05-12	29.888 mi
Registration #8	2012-05-09	33.828 mi
Registration #9	2013-05-08	37.448 mi
Registration #10	2014-05-09	40.452 mi
Registration #11	2015-05-05	43.617 mi
Registration #12	2016-04-18	47.054 mi
Registration #13	2016-05-01	50.500 mi
Registration #14	2016-05-01	50.500 mi
Registration #15	2016-05-01	50.500 mi
Registration #16	2016-05-01	50.500 mi
Registration #17	2016-05-01	50.500 mi
Registration #18	2016-05-01	50.500 mi
Registration #19	2016-05-01	50.500 mi
Registration #20	2016-05-01	50.500 mi
Registration #21	2016-05-01	50.500 mi
Registration #22	2016-05-01	50.500 mi
Registration #23	2016-05-01	50.500 mi

More info >



Dimensions & weight

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198340087137