



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO GHIA TDCI 125
Colour	Silver
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-17
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-09-27
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	32
Total items failed	7

MOT #17 2022-09-28 16:39

MOT test number 448576652689

Result ✓ Passed

Next expiry date 2023-09-27

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

Minor Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Front Windscreen wiper blade defective both (3.4 (b) (i))

MOT #16 2021-09-22 15:03

MOT test number 219943678067

Result ✓ Passed

MOT #15 2021-09-22 15:03

MOT test number 501024931294

Result ✗ Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14** 2021-07-17 15:12**MOT test number** 225614625108**Result** ✗ Failed

- DANGEROUS** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- DANGEROUS** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #13 2020-12-30 16:02**MOT test number** 344651358692**Result** ✓ Passed**MOT #12** 2019-12-23 09:07**MOT test number** 901569925826**Result** ✓ Passed**MOT #11** 2019-12-23 09:07**MOT test number** 123153762253**Result** ✗ Failed

- Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #10 2018-12-18 14:03**MOT test number** 975764858362**Result** ✓ Passed

**MOT #9**

2017-12-14 16:46

MOT test number

301175909807

Result

✓ Passed

- Advice** (4.1.E.1) Offside Front Tyre worn close to the legal limit very worn on outer edges but not showing cords
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)
- Advice** Nearside Rear tyre slightly perished
- Advice** (4.1.E.1) Nearside Front Tyre worn close to the legal limit very worn on outer edges but not showing cords
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8

2016-12-20 09:33

MOT test number

154641822106

Result

✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened both front corroded (3.5.1i)
- Advice** Nearside door mirror loose
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** (2.4.G.2) Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
- Advice** Offside door mirror broken but not causing sharp edge
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #7

2015-12-15 14:24

MOT test number

302977351186

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Child seat fitted at time of test not allowing full inspection of belts
- Advice** (2.4.G.2) Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

**MOT #6** 2015-12-15 09:59**MOT test number** 416074155692**Result** ✗ Failed**Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Child seat fitted at time of test not allowing full inspection of belts**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2014-12-16 12:33**MOT test number** 257740554331**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2014-01-02 14:22**MOT test number** 787712004095**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #3** 2014-01-02 12:05**MOT test number** 135342904498**Result** ✗ Failed**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Headlamp aim too high (1.8)**MOT #2** 2012-12-27 09:59**MOT test number** 505102062397**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-11-03 15:09**MOT test number** 468137801350**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA58OLR
Plate since	2019-03-28
Current registration	EA58OLR
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-14
Last registration	2022-09-28
Complete history	See info



Registration #1	2008-11-14	25 mi
Registration #2	2011-11-03	29.211 mi
Registration #3	2012-12-27	40.132 mi
Registration #4	2014-01-02	47.706 mi
Registration #5	2014-01-02	47.706 mi
Registration #6	2014-12-16	53.156 mi
Registration #7	2015-12-15	59.746 mi
Registration #8	2015-12-15	59.746 mi
Registration #9	2016-12-20	65.766 mi
Registration #10	2017-12-14	71.246 mi
Registration #11	2018-01-01	71.246 mi
Registration #12	2018-01-01	71.246 mi
Registration #13	2018-01-01	71.246 mi
Registration #14	2018-01-01	71.246 mi
Registration #15	2018-01-01	71.246 mi
Registration #16	2018-01-01	71.246 mi
Registration #17	2018-01-01	71.246 mi
Registration #18	2018-01-01	71.246 mi
Registration #19	2018-01-01	71.246 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1457 mm
Length	4830 mm
Wheel base	2754 mm
Max. allowed weight	2265 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	8E21146