





report date: 2024-03-28

General information

| Make | RENAULT |
|---------------------|---------------------------------|
| Model | ESPACE AUTHENTIQUE DCI (120BHP) |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 112 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 120 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 31.7 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 40.4 mpg |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 4

Date 2021-07-04

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 3

| Date 2021-06-25 | |
|-----------------|--|
|-----------------|--|

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-06-18

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date CarCheck.co.uk 2021-06-11 page 2/11

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk



report date: 2024-03-28

MOT history

MOT #17 2021-02-04 16:48 **MOT** test number 685629310158 Result X Failed Fail Nearside Rear Brake disc missing (1.1.14 (c)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #16

MOT test number

Result

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Suspension component ball joint has slight play (5.3.4 (a) (i))

MOT #14

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit outer edge (4.1.E.1)

CarCheck.co.uk page 3/11



Result

GD03VHF

report date: 2024-03-28

× Failed

MOT #13 2015-07-11 10:13

MOT test number 758092595189

MOT #12 2015-07-11 09:58

MOT test number 317732095197

Result ★ Failed

Fail Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #11 2014-07-07 17:11

MOT test number 216648184408

Result ✓ Passed

MOT #10 2013-07-04 12:38

MOT test number 359125583115

Result
✓ Passed

MOT #9 2012-07-20 09:41

MOT test number 807132902239

Result ✓ Passed

MOT #8 2012-07-13 10:50

MOT test number 537915892188

Fail Offside Track rod end ball joint has excessive play (2.2.B.1f)

Fail Nearside Track rod end ball joint has excessive play (2.2.B.1f)

CarCheck.co.uk page 4/11



Result

GD03VHF

report date: 2024-03-28

✓ Passed

| MOT #7 | 2011-07-12 15:48 |
|---|------------------|
| MOT test number | 685453491142 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2011-07-12 14:45 |
| MOT test number | 677093191144 |
| Result | X Failed |
| Fail Offside Track rod end ball joint has excessive play (2.2.B.1f) | |
| | |
| MOT #5 | 2010-07-02 10:05 |
| MOT test number | 181433780199 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2009-07-03 10:01 |
| MOT test number | 363764489185 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2008-07-07 15:51 |
| MOT test number | 672089488163 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2007-07-21 10:59 |
| MOT test number | 162232107271 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2006-07-24 10:47 |
| MOT test number | 394395206445 |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| Owner | history |
|--------|---------|
| OWITEL | HISLULY |

| For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
|--|-------------|
| | |
| MARKET CONTRACTOR CONT | |
| *************************************** | |
| *********** | |
| | |
| | |
| | |
| *************************************** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this RENAULT had different number plates. | |
| | |
| Number of plates | |
| Current registration | UK SIP |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 21 |
| First mileage registration | 2003-07-24 |
| Last registration | 2021-02-04 |
| Complete history | See info |



| Registration #1 | 2003-07-24 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2006-07-24 | 30.254 mi |
| Registration #3 | 2007-07-21 | 36.513 mi |
| Registration #4 | 2008-07-07 | 41.033 mi |
| Registration #5 | 2009-07-03 | 46.121 mi |
| Registration #6 | 2010-07-02 | 51.546 mi |
| Registration #7 | 2011-07-12 | 57.067 mi |
| Registration #8 | 2011-07-12 | 57.067 mi |
| Registration #9 | 2012-07-20 | 63.109 mi |
| Registration #10 | 2013-07-04 | 67.784 mi |
| Registration #11 | 2014-07-07 | 75.533 mi |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.177 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 11.777 es |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 ms |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 2104 mm |
|---------------------|---------|
| Height | 1782 mm |
| Length | 4661 mm |
| Wheel base | 2803 mm |
| Max. allowed weight | 2505 kg |

Additional information

| Fuel tank capacity | 83 |
|---------------------------------|--------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number CarCheck.co.uk | C013007 page 11/11 |