



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 R-DESIGN AWD
Colour	Black
Year of manufacture	2014
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.4 mpg
CO2 emission	215 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-04-13
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	12
Total items failed	0

MOT #10	2024-04-10 11:47
MOT test number	793642348521
Result	✓ Passed
Next expiry date	2025-04-13

MOT #9	2023-04-04 14:57
MOT test number	722506714781
Result	✓ Passed

MOT #8	2022-04-04 09:53
MOT test number	297593260342
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2021-04-14 14:42
MOT test number	804700122723
Result	✓ Passed

MOT #6	2020-12-08 14:24
MOT test number	798578598675
Result	✓ Passed

**MOT #5**

2020-03-14 11:36

MOT test number

169095809005

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #4

2020-03-13 17:22

MOT test number

491754858447

Result

✗ Failed

Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #3

2019-03-06 09:30

MOT test number

248348561252

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2

2018-03-01 09:14

MOT test number

938134948230

Result

✓ Passed



MOT #1	2017-03-08 09:02
MOT test number	341006564205
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
13 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	13 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-14
Last registration	2024-04-10
Complete history	See info



Registration #1	2014-03-14	29 mi
Registration #2	2017-03-08	31.031 mi
Registration #3	2018-03-01	49.688 mi
Registration #4	2019-03-06	66.544 mi
Registration #5	2020-03-13	85.365 mi
Registration #6	2020-03-14	85.366 mi
Registration #7	2020-03-20	85.377 mi
Registration #8	2020-03-20	85.377 mi
Registration #9	2020-03-20	85.377 mi
Registration #10	2020-03-20	85.377 mi
Registration #11	2020-03-20	85.377 mi
Registration #12	2020-03-20	85.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2112 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2171 kg
Max. allowed weight	2770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

1413567