



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60)
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2022-08-05
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-14
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	42
Total items failed	3

MOT #14	2023-08-09 11:30
MOT test number	914407039492
Result	✓ Passed
Next expiry date	2024-08-14
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm, worn inner edge, stepped and has nail (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge stepped (5.2.3 (e))
Advice	Offside front shock absorber casing corroded

MOT #13	2022-08-15 16:33
MOT test number	920992944541
Result	✓ Passed
Advice	Under-body covered in under-seal.
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))
Advice	Parking brake has slight reserve travel.
Advice	Shock absorber corroded. OSF + NSF + OSR
Advice	Rear Drive shaft's slightly corroded.
Advice	Rear Brake hose has slight corrosion to ferrule Both. (1.1.12 (f) (i))

**MOT #12** 2022-03-04 13:33**MOT test number** 692273509777**Result** ✓ Passed**MOT #11** 2021-06-29 15:16**MOT test number** 823787088195**Result** ✓ Passed**MOT #10** 2020-06-19 14:58**MOT test number** 903436037274**Result** ✓ Passed**MOT #9** 2020-06-19 14:58**MOT test number** 743328363128**Result** ✗ Failed

Pass with rectification Headlamp aim projected beam image is obviously incorrect Bulb re-set in holder.
(4.1.2 (c))

Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all
lamps New bulb inserted (4.7.1 (b) (ii))

MOT #8 2019-06-13 08:04**MOT test number** 232739157665**Result** ✓ Passed

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement close to
excessive (5.3.4 (a) (i))

**MOT #7** 2018-08-08 11:11**MOT test number** 272126383231**Result** ✓ Passed

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))

Advice Mixture of summer and winter tyres fitted

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice O/S/F AND O/S/R tyres worn to 3mm

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6 2018-08-08 08:35**MOT test number** 666633388201**Result** ✗ Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Winter tyres fitted

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

Advice O/S/F AND O/S/R tyres worn to 3mm

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D-bush (5.3.4 (a) (i))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #5

2017-07-27 10:18

MOT test number

420457832830

Result

✓ Passed

- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4

2016-07-22 14:08

MOT test number

768525974388

Result

✓ Passed

- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2016-07-22 10:50**MOT test number** 942258020033**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2015-07-31 10:50**MOT test number** 337302615479**Result** ✓ Passed**Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2014-08-05 11:37**MOT test number** 827837514252**Result** ✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	SC11JWY
Plate since	2019-03-28
Current registration	SC11JWY
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-08-09
Last registration	2023-08-09
Complete history	See info



Registration #1	2011-08-09	7 mi
Registration #2	2014-08-05	34.884 mi
Registration #3	2015-07-31	47.405 mi
Registration #4	2016-07-22	57.428 mi
Registration #5	2016-07-22	57.428 mi
Registration #6	2017-07-27	69.659 mi
Registration #7	2018-08-08	82.545 mi
Registration #8	2018-08-08	82.545 mi
Registration #9	2019-08-08	95.431 mi
Registration #10	2019-08-08	95.431 mi
Registration #11	2019-08-08	95.431 mi
Registration #12	2019-08-08	95.431 mi
Registration #13	2019-08-08	95.431 mi
Registration #14	2019-08-08	95.431 mi
Registration #15	2019-08-08	95.431 mi
Registration #16	2019-08-08	95.431 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1365 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4

Engine number	71407850
---------------	----------