





report date: 2024-03-28

## General information

| Make                | MINI                             |
|---------------------|----------------------------------|
| Model               | COOPER S COOPER S E ALL4 CLASSIC |
| Colour              | Grey                             |
| Year of manufacture | 2019                             |
| Top speed           | 123 mph                          |
| Gearbox             | 6 speed automatic                |

# Engine & fuel consumption

| Power                | 221 BHP             |
|----------------------|---------------------|
| Max. torque          | 385 Nm at 4.300 rpm |
| Engine capacity      | 1.499 сс            |
| Cylinders            | 3                   |
| Fuel type            | Hybrid / Electric   |
| 71.                  | Trybria / Electric  |
| Consumption combined | 97.4 mpg            |
| **                   | •                   |



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2022-05-18

Pictures 8

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2022-05-13

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



WR19DZD report date: 2024-03-28

MOT history

| MOT expiry date    | 2025-03-23 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 4          |
| Failed MOT tests   | 1          |
| Total advice items | 4          |
| Total items failed | 1          |

| MOT #5           | 2024-03-15 10:40 |
|------------------|------------------|
| MOT test number  | 736246520797     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-03-23       |

| MOT #4  | 2023-03-24 10:07  |   |
|---------|---|---|
| MOT tes | t number 246037128359   | _ |
| Result  | ✓ Passed  |   |
| Advice  | Under tray fitted   |   |
| Advice  | Offside Rear Tyre slightly damaged/cracking or perishing light perishing on edge (5.2.3 (d) (ii)) |   |

| MOT #3                   |   | 2023-03-24 10:07                      |
|--------------------------|---|---------------------------------------|
| MOT test number          |   | 947437956185                          |
| Result                   |   | <b>X</b> Failed                       |
| Advice Offside Rear Tyr  | e slightly damaged/cracking or perishing ligh | nt perishing on edge (5.2.3 (d) (ii)) |
| Pass with rectification  | Front Windscreen wiper does not clear the     | windscreen effectively (3.4 (b) (ii)) |
| Advice Under tray fitted |   |                                       |

| MOT #2          | 2022-06-14 07:53 |
|-----------------|------------------|
| MOT test number | 357386046815     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/11



report date: 2024-03-28

 MOT #1
 2022-03-21 15:20

 MOT test number
 924245974420

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 June |
|------------------|--------------------|
| Days left        | 34                 |
| MOT expiry date  | 23 March 2025      |
| Full MOT history | See MOT history    |

#### Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



funda scincos

WR19DZD

report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MINI had different number plates. ober of plates

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 8          |
| First mileage registration | 2019-03-31 |
| Last registration          | 2024-03-15 |
| Complete history           | See info   |



| Registration #1 | 2019-03-31 | 24 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2022-03-21 | 22.778 mi |
| Registration #3 |            | 9.777 es  |
| Registration #4 |            | 11.777 es |
| Registration #5 |            | 11.777 es |
| Registration #6 |            | 11.777 es |
| Registration #7 |            | 11.777 es |
| Registration #8 |            | 71.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 79%             |
| Children       | 73%             |
| Pedestrian     | 66%             |
| Safety systems | 56%             |
| Overall rating | 71%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1822 mm |
|---------------------|---------|
| Height              | 1557 mm |
| Length              | 4299 mm |
| Max. allowed weight | 2270 kg |

## Additional information

| Number of seats | 5        |
|-----------------|----------|
| Number of axles | 2        |
| Engine number   | F420K066 |

CarCheck.co.uk page 11/11