





General information

Engine & fuel consumption

| Power | 84 BHP |
|-------------------------|---------------------|
| Max. torque | 121 Nm at 4.000 rpm |
| Engine capacity | 1.248 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 114 g/km |
| CO2 label | С |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-02-01 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-02-07 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 9 |
| Total items failed | 4 |

| MOT #10 | 2024-01-08 12:56 |
|--|----------------------------------|
| MOT test number | 736413424042 |
| Result | ✓ Passed |
| Next expiry date 2025-02-07 | |
| Minor Registration plate lamp inoperative in the case of multiple lamps of | or light sources (4.7.1 (b) (i)) |

| MOT #9 | 2023-02-08 16:13 |
|----------|--|
| MOT test | number 795631363944 |
| Result | ✓ Passed |
| Minor | Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |

| MOT #8 | 2023-02-07 17:16 |
|--|------------------|
| MOT test number | 464851047717 |
| Result | 🗙 Failed |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) | |
| Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) | |





| MOT #7 | 2022-02-02 11:28 |
|---|---------------------|
| MOT test number | 997514286780 |
| Result | Passed |
| Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge also cracking or | n edges (5.2.3 (e)) |
| MOT #6 | 2021-01-11 08:42 |
| MOT test number | 726720333249 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-02-24 11:12 |
| MOT test number | 659326397862 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2019-03-11 14:20 |
| MOT test number | 811296792452 |
| Result | ✓ Passed |
| MOT #3 | 2018-03-15 16:28 |
| MOT test number | 349985407731 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2018-03-02 14:37 |
| MOT test number | 642449750935 |
| Result | 🗙 Failed |
| Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Advice Offside Front Brake pad(s) wearing thin (3.5.1g) | |
| Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) | |





| MOT #1 | 2017-02-20 11:15 |
|-----------------------------------|------------------|
| MOT test number | 996923384784 |
| Result | ✓ Passed |
| Advice Nearside Rear Nail in tyre | |



Tax & MOT check

| ✓ Taxed Tax due: 1 February 2025 | ✓ MOT Expires: 7 February 2025 |
|---|---|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 7 February 2025 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|----------------|
| Band | C |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | FERRE |
| Category | A PANAL |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | ant |
| Туре | |
| | |

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2014-03-20 |
| Last registration | 2024-01-08 |
| Complete history | See info |



| Registration #1 | 2014-03-20 | 20 mi |
|-------------------------------------|------------|--|
| Registration #2 | 2017-02-20 | 25.763 mi |
| Registration #3 | 2018-03-02 | 34.162 mi |
| Registration #4 | 2018-03-15 | 34.505 mi |
| Registration #5 | 2019-03-11 | 42.754 mi |
| Registration #6 | 2020-02-24 | 50.333 mi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 10.200 est |
| | | |
| Registration #9 | | 11.777 mi |
| Registration #9 Registration #10 | | 10.000 est |
| | | 10.000 est 10.000 est 10.000 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 92% |
| Children | 84% |
| Pedestrian | 46% |
| Safety systems | 86% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1720 mm |
| Height | 1455 mm |
| Length | 4045 mm |
| Wheel base | 2570 mm |
| Kerb weight | 1203 kg |
| Max. allowed weight | 1560 kg |
| Additional information | |
| Fuel tank capacity | 43 |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|--------------|
| Engine number | G4LAEP057455 |