



KM09NKR

report date: 2024-03-29

General information

Make	FORD
Model	RANGER DCB 4X4
Colour	Black
Year of manufacture	-
Gearbox	5 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN

**MOT history**

MOT #13	2020-02-01 15:48
MOT test number	528411797422
Result	✓ Passed
Next expiry date	2021-01-31

MOT #12	2019-01-09 10:41
MOT test number	886998986933
Result	✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2018-01-06 15:48
MOT test number	719850143626
Result	✓ Passed

MOT #10	2016-11-28 11:00
MOT test number	666608777421
Result	✓ Passed




MOT #9	2015-12-07 15:32
MOT test number	774057504517
Result	✓ Passed

MOT #8	2015-12-07 10:40
MOT test number	996537739820
Result	✗ Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Front wheel bearing has excessive play (2.5.A.3c)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-12-11 15:50**MOT test number** 687705944336**Result**  Passed**MOT #6** 2014-12-11 09:29**MOT test number** 159805444378**Result**  Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2013-09-24 15:49**MOT test number** 876907263273**Result**  Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Steering pivot point has slight play (2.2.B.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Rear wheel bearing has slight play (2.6.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4**

2013-09-20 15:03

MOT test number

885773263236

Result

✓ Passed

Advice Nearside Steering system has slight free play detected at steering wheel (2.2.A.1a)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Steering system has slight free play detected at steering wheel (2.2.A.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3**

2013-09-18 10:00

MOT test number

776401263204

Result

✗ Failed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Steering system has slight free play detected at steering wheel (2.2.A.1a)**Fail** Offside Front Seat belt retracting mechanism defective (5.2.5b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Offside Steering system has slight free play detected at steering wheel (2.2.A.1a)**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)



MOT #2	2012-06-13 16:59
MOT test number	847675362143
Result	✓ Passed

MOT #1	2012-06-13 16:59
MOT test number	957825162180
Result	✗ Failed
Pass with rectification	Exhaust emits an excessive level of metered smoke (7.4.B.3a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	KM09NKR
Plate since	2019-09-29
Current registration	KM09NKR
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-06-02
Last registration	2020-02-01
Complete history	See info



Registration #1	2009-06-02	16 mi
Registration #2	2012-06-13	60.871 mi
Registration #3	2013-09-18	76.823 mi
Registration #4	2013-09-20	76.828 mi
Registration #5	2013-09-24	76.858 mi
Registration #6	2014-12-11	116.801 mi
Registration #7	2014-12-11	116.801 mi
Registration #8	2015-05-20	116.877 mi
Registration #9	2015-05-20	116.877 mi
Registration #10	2015-05-20	116.877 mi
Registration #11	2015-05-20	116.877 mi
Registration #12	2015-05-20	116.877 mi
Registration #13	2015-05-20	116.877 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	113188