



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA EXCLUSIVE 16V PICASSO E4
Colour	Red
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	191 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.6 mpg
Consumption extra urban	44.1 mpg
Consumption combined	32.8 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-06
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-22
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	43
Total items failed	0

MOT #19	2024-01-23 14:57
MOT test number	811920961270
Result	✓ Passed
Next expiry date	2025-01-22
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
Advice	Both inner and outer sills undersealed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18	2024-01-23 13:35
MOT test number	329193862139
Result	✗ Failed
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Both inner and outer sills undersealed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))

**MOT #17**

2024-01-05 16:23

**MOT test number**

531254625393

**Result****✗ Failed**

**MAJOR** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

**Advice** Nearside Front Drag link end ball joint has slight play (2.1.3 (b) (i))

**MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MAJOR** Offside Front Drag link end ball joint has excessive play (2.1.3 (b) (i))

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Minor** Rear Registration plate lamp throwing direct white light to the rear (4.7.1 (a))

**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2023-01-04 14:50

**MOT test number**

430538371886

**Result****✓ Passed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2023-01-03 14:51**MOT test number** 517759488345**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**DANGEROUS** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #14** 2021-12-10 13:39**MOT test number** 807852453022**Result** ✓ Passed**MOT #13** 2021-03-05 15:25**MOT test number** 182493968392**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2020-08-28 11:54**MOT test number** 393501074158**Result** ✓ Passed

**MOT #11** 2020-08-27 15:57**MOT test number** 204933967445**Result** ✗ Failed**MAJOR** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear exhaust bracket broken**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10** 2019-09-05 09:40**MOT test number** 940719538031**Result** ✓ Passed**MOT #9** 2018-06-05 12:32**MOT test number** 321838684432**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-01-19 17:47**MOT test number** 996093775063**Result** ✓ Passed**MOT #7** 2015-11-05 15:40**MOT test number** 361846841586**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-10-11 10:20**MOT test number** 925884284246**Result** ✓ Passed

**MOT #5** 2013-09-25 11:16**MOT test number** 485808163274**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-09-27 11:29**MOT test number** 277241872260**Result** ✓ Passed**MOT #3** 2011-09-28 11:21**MOT test number** 389191671401**Result** ✓ Passed**Notice** Both side rear brake disc corroded**MOT #2** 2010-10-11 12:18**MOT test number** 733964880242**Result** ✓ Passed**MOT #1** 2009-10-05 10:32**MOT test number** 713908079200**Result** ✓ Passed**Advice** Offside Rear brake disc slightly pitted (3.5.1h)**Advice** Nearside Rear brake disc slightly pitted (3.5.1h)**Notice** Oil leak



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 February 2025

✓  
**MOT**

**Expires:**  
22 January 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	22 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	VN56UKX
Plate since	2024-03-28
Current registration	VN56UKX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-11-25
Last registration	2024-01-23
Complete history	<a href="#">See info</a>



Registration #1	2006-11-25	6 mi
Registration #2	2009-10-05	10.048 mi
Registration #3	2010-10-11	15.724 mi
Registration #4	2011-09-28	20.177 mi
Registration #5	2012-09-27	25.559 mi
Registration #6	2013-09-25	29.505 mi
Registration #7	2014-10-11	31.906 mi
Registration #8	2015-11-05	34.768 mi
Registration #9	2017-01-19	36.747 mi
Registration #10	2018-06-05	41.865 mi
Registration #11	2019-09-05	43.483 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2021-05-20	46.277 mi
Registration #14	2022-05-20	47.277 mi
Registration #15	2023-05-20	48.277 mi
Registration #16	2024-01-23	49.277 mi
Registration #17	2024-01-23	49.277 mi
Registration #18	2024-01-23	49.277 mi
Registration #19	2024-01-23	49.277 mi
Registration #20	2024-01-23	49.277 mi
Registration #21	2024-01-23	49.277 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1245 kg
Max. allowed weight	1832 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LH4G1454817