



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO GP
Colour	Grey
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-03
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-09-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	70
Total items failed	7

MOT #152023-09-16 07:01

MOT test number642618603765

Result✓ Passed

Next expiry date2024-09-15

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Surface rust underneath body
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Minor** Front Windscreen wiper blade defective smearing (3.4 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))



MOT #14

2023-09-09 07:44

MOT test number

631729994444

Result

✖ Failed

Minor

Front Windscreen wiper blade defective smearing (3.4 (b) (i))

Advice

Coil spring corroded all (5.3.1 (b) (i))

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

DANGEROUS

Front Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))

Advice

Oil leak, but not excessive engine (8.4.1 (a) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Front Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice

Surface rust underneath body

Advice

Front Suspension arm corroded but not seriously weakened both (5.3.3 (b) (i))

DANGEROUS

Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice

Oil leak, but not excessive gearbox (8.4.1 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))



MOT #13

2021-08-16 16:51

MOT test number

190079898203

Result		✓ Passed
Advice	Nearside Rear Valve stem slightly damaged (5.2.3 (j))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))	
Advice	Oil leak, but not excessive transmission (8.4.1 (a) (i))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

**MOT #12**

2021-08-16 11:49

**MOT test number**

686054864061

**Result****✗ Failed**

- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive transmission (8.4.1 (a) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2020-08-14 09:46

**MOT test number**

254783149467

**Result****✓ Passed**

- Advice** Oil leak, but not excessive sump (8.4.1 (a) (i))
- Advice** Offside Rear Nail in tyre
- Advice** Oil leak, but not excessive drive shaft seal (8.4.1 (a) (i))

**MOT #10**

2019-08-14 09:20

**MOT test number**

985301224866

**Result****✓ Passed**

**MOT #9** 2018-08-16 09:14**MOT test number** 959286636280**Result** ✓ Passed**MOT #8** 2018-08-15 13:20**MOT test number** 200805479052**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Obligatory mirror missing (3.3 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-04-13 09:46**MOT test number** 242839164270**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Nearside Non - obligatory mirror outer casing missing**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Noise from clutch bearing / gearbox

**MOT #6** 2018-04-12 16:16**MOT test number** 675892738728**Result** ✗ Failed**Fail** Rear brakes release unevenly (3.7.B.4)**Advice** Nearside Non - obligatory mirror outer casing missing**Advice** Nearside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Fail** Rear brake application uneven (3.7.B.2)**Fail** Rear Brakes imbalanced across an axle 33% (3.7.B.5b)**Advice** Noise from clutch bearing / gearbox**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #5** 2017-04-20 11:03**MOT test number** 756634417557**Result** ✓ Passed**Advice** Nearside Rear tyre cracking**Advice** Offside Rear tyre cracking**MOT #4** 2016-04-15 10:07**MOT test number** 705231298276**Result** ✓ Passed



**MOT #3**

2015-04-07 09:57

**MOT test number**

409897495007

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Notice** Offside rear tyre nailed (R)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside front tyre heavily perished**Notice** Rear exhaust silencer outer casing corroded**MOT #2**

2014-04-15 13:49

**MOT test number**

285105604195

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1**

2014-04-15 12:23

**MOT test number**

577675004173

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too low (1.8)**Notice** O/s wiper blade split**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	187
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-28
Last registration	2023-09-16
Complete history	<a href="#">See info</a>



Registration #1	2011-04-28	27 mi
Registration #2	2014-04-15	18.345 mi
Registration #3	2014-04-15	18.345 mi
Registration #4	2015-04-07	25.165 mi
Registration #5	2016-04-15	30.664 mi
Registration #6	2017-04-20	34.603 mi
Registration #7	2018-04-12	39.333 mi
Registration #8	2018-04-13	39.333 mi
Registration #9	2018-08-15	40.315 mi
Registration #10	2019-05-29	51.277 mi
Registration #11	2019-05-29	51.277 mi
Registration #12	2019-05-29	51.277 mi
Registration #13	2019-05-29	51.277 mi
Registration #14	2019-05-29	51.277 mi
Registration #15	2019-05-29	51.277 mi
Registration #16	2019-05-29	51.277 mi
Registration #17	2019-05-29	51.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	6332630