



report date: 2024-03-29

General information

| | |
|---------------------|------------------|
| Make | VOLVO |
| Model | V50 SE LUX D S40 |
| Colour | Black |
| Year of manufacture | 2008 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 134 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 153 g/km |
| CO2 label | G |





MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-02-16 |
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 3 |

MOT #13 2021-02-10 15:21

MOT test number 751181776544

Result ✓ Passed

Next expiry date 2022-02-16

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12 2021-02-10 15:20

MOT test number 952465089231

Result ✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Pass with rectification Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #11** 2020-02-17 14:29**MOT test number** 829214583422**Result** ✓ Passed**MOT #10** 2019-03-11 14:51**MOT test number** 894303397369**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2019-03-11 09:39**MOT test number** 666745907653**Result** ✗ Failed**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #8** 2018-03-29 09:37**MOT test number** 927166890813**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2017-03-27 13:04**MOT test number** 456669086646**Result** ✓ Passed**MOT #6** 2016-03-22 13:27**MOT test number** 859021487107**Result** ✓ Passed

**MOT #5** 2015-03-25 09:25**MOT test number** 129554485090**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2014-03-21 10:54**MOT test number** 479760584011**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-04-02 09:30**MOT test number** 386972793048**Result** ✓ Passed**Notice** Nail in nearside rear tyre**MOT #2** 2012-04-03 09:20**MOT test number** 636204892097**Result** ✓ Passed**MOT #1** 2011-04-04 09:19**MOT test number** 337934991062**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
29 March 2021

✕
MOT

Expired:
16 February 2022

| | |
|------------------|---------------------------------|
| Tax status | Expired at 29 March 2021 |
| Days left | 1128 days too late |
| MOT expiry date | 16 February 2022 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BN08RVZ |
| Plate since | 2024-03-29 |
| Current registration | BN08RVZ |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2008-03-20 |
| Last registration | 2021-02-10 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2008-03-20 | 26 mi |
| Registration #2 | 2011-04-04 | 120.211 mi |
| Registration #3 | 2012-04-03 | 129.227 mi |
| Registration #4 | 2013-04-02 | 133.051 mi |
| Registration #5 | 2014-03-21 | 137.762 mi |
| Registration #6 | 2015-03-25 | 143.098 mi |
| Registration #7 | 2016-03-22 | 146.728 mi |
| Registration #8 | 2017-03-20 | 151.357 mi |
| Registration #9 | 2018-03-20 | 156.987 mi |
| Registration #10 | 2019-03-20 | 162.617 mi |
| Registration #11 | 2020-03-20 | 168.247 mi |
| Registration #12 | 2021-03-20 | 173.877 mi |
| Registration #13 | 2022-03-20 | 179.507 mi |
| Registration #14 | 2023-03-20 | 185.137 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1457 kg |
| Max. allowed weight | 1940 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|--------|
| Number of axles | 2 |
| Engine number | 411629 |