





report date: 2024-03-29

General information

Make	MERCEDES
Model	CL 500 500
Colour	Black
Year of manufacture	2007
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	382 BHP
Max. torque	530 Nm at 2.800 rpm
Engine capacity	5.462 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.6 mpg
Consumption extra urban	33.2 mpg
Consumption combined	23.3 mpg
CO2 emission	288 g/km
CO2 label	М



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-01-17

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2024-04-17
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	10
Total items failed	3

MOT #15	2023-04-18 14:26
MOT test number	906102081696
Result	✓ Passed
Next expiry date	2024-04-17

MOT #14	2021-12-28 13:57
MOT test number	435617875372
Result	✓ Passed

MOT #13		2020-11-16 11:42
MOT test	number	601891046601
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2019-05-20 11:38
MOT test number	397951639082
Result	✓ Passed
MOT #11	2018-05-21 11:30

MOT #11	2018-05-21 11:30
MOT test number	633850134915
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #10 2017-05-11 14:48

MOT test number 551105206900

Result ✓ Passed

Advice Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

Advice Oil leak

Advice Offside Front Front suspension has slight play in a lower suspension ball joint sprink link (2.5.B.1a)

Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #9 2017-05-10 13:30

MOT test number 804024122685

Result X Failed

Fail Offside Front Torque/reaction arm has a deteriorated rubber bush resulting in excessive movement (2.4.G.2)

Advice Oil leak

Advice Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

Advice Offside Front Front suspension has slight play in a lower suspension ball joint sprink link (2.5.B.1a)

Advice Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

Fail Nearside Front brake caliper leaking (3.6.A.1)

MOT #8 2016-03-22 10:22

MOT test number 991254641223

Result ✓ Passed

MOT #7 2015-05-08 11:49

MOT test number 217728325106

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #6

MOT test number

Result

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
MOT #5	2014-01-27 12:01
MOT test number	189257524409
Result	✓ Passed
MOT #4	2013-01-25 09:11
MOT test number	615755723052
Result	✓ Passed
MOT #3	2012-02-20 11:10
MOT test number	516051852058
Result	✓ Passed
MOT #2	2011-02-24 13:34
MOT test number	116515751062
Result	✓ Passed
MOT #1	2010-03-22 11:20
MOT test number	354521380010
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check

Tax expired: 23 April 2021



X MOT

Expired: 17 April 2024

Tax status	Expired at 23 April 2021
Days left	1103 days too late
MOT expiry date	17 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloane.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NEW
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-05-24
Last registration	2023-04-18
Complete history	See info



Registration #1	2007-05-24	13 mi
Registration #2	2010-03-22	13.176 mi
Registration #3	2011-02-24	18.075 mi
Registration #4	2012-02-20	23.039 mi
Registration #5	2013-01-25	29.247 mi
Registration #6	2014-01-27	36.613 mi
Registration #7	2015-05-08	46.438 mi
Registration #8	2015-05-08	46.438 mi
Registration #9	2016-03-22	52.930 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D. 2777 -esc

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

Width	1871 mm
Height	1418 mm
Length	5065 mm
Wheel base	2955 mm
Kerb weight	1995 kg
Max. allowed weight	2510 kg

Additional information

Fuel tank capacity	90 I
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	273961

CarCheck.co.uk page 12/12