





report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 SE NAV
Colour	White
Year of manufacture	2016
Top speed	130 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	124 g/km
CO2 label	D



CarCheck.co.uk page 1/11



LR66RYX

report date: 2024-03-29

Internet history

Entry 3

Date 2022-05-24

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-03-29

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-06

Pictures 25

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



LR66RYX

report date: 2024-03-29

MOT history

MOT expiry date	2024-06-15
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	9
Total items failed	4

MOT #8	2023-06-16 13:12
MOT test number	765839528368
Result	✓ Passed
Next expiry date	2024-06-15
Minor Offside Registration plate lamp inoperative in the case of multiple lamps (i))	or light sources (4.7.1 (b)

MOT #7	2023-06-15 09:34
MOT test number	412431140842
Result	× Failed
Minor (i)) Offside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)
Fail Offside Side repeater not working (4.4.1 (a) (ii))	

MOT #6	2022-06-16 07:46
MOT test number	410731694586
Result	✓ Passed

MOT #5		2021-05-18 16:12
MOT test	number	102800744790
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

CarCheck.co.uk page 3/11



LR66RYX

report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification

Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2020-07-31 14:58 **MOT** test number 409858245205 Result ✓ Passed **MOT** #2 2020-07-31 08:28 **MOT** test number 649066548394 Result × Failed **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1	2019-08-12 09:59
MOT test number	396255153476
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

o mile motory	
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	SK (
Plate since	
Current registration	NK WIS
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte at Info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-09-28
Last registration	2023-06-16
Complete history	See info



Registration #1	2016-09-28	8 mi
Registration #2	2019-08-12	75.438 mi
Registration #3	2020-07-31	88.331 mi
Registration #4	2020-07-31	83.333 mi
Registration #5	2021-05-18	95.548 mi
Registration #6	2021-05-18	95.548 mi
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		0.70 es
Registration #12		11.777 au

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1781 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles2Engine number1824431