



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 EXECUTIVE
Colour	Green
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.0 mpg
CO2 emission	239 g/km
CO2 label	L





MOT history

MOT expiry date	2024-08-22
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	51
Total items failed	26

MOT #24	2023-08-15 15:18
MOT test number	386420503829
Result	✓ Passed
Next expiry date	2024-08-22
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Both front tyres wearing off inner edges
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Anti skid warning message on dash

MOT #23	2022-08-23 11:53
MOT test number	161502653803
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #22** 2021-07-27 09:37**MOT test number** 752048010524**Result** ✓ Passed**MOT #21** 2020-08-13 09:04**MOT test number** 128013173303**Result** ✓ Passed**MOT #20** 2020-08-11 10:34**MOT test number** 240965227935**Result** ✗ Failed

- Fail** Parking brake inoperative on one side both sides (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #19 2019-08-01 10:17**MOT test number** 193835406539**Result** ✓ Passed

- Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #18 2018-08-13 15:39**MOT test number** 166861211765**Result** ✓ Passed

**MOT #17**

2018-08-13 09:03

MOT test number

239830449699

Result**✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Play in steering rack inner joint(s)**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Offside Rear Road wheel fixing missing (5.2.1 (a) (i))**MOT #16**

2017-07-26 11:36

MOT test number

366829192307

Result**✓ Passed****MOT #15**

2017-07-25 11:07

MOT test number

280378286035

Result**✗ Failed****Fail** Fuel tank leaking (7.2.3)**Fail** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #14** 2016-08-15 08:29**MOT test number** 520335491022**Result** ✓ Passed

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt boot rear seat
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt boot rear seats

MOT #13 2015-08-13 15:40**MOT test number** 128365625202**Result** ✓ Passed**MOT #12** 2015-08-13 10:28**MOT test number** 355905525403**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.C.1b)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #11**

2014-08-22 14:17

MOT test number

326764434225

Result

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** N/s/r tyre worn around outer edge
- Notice** Nail in nearside rear tyre
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #10

2014-08-22 09:14

MOT test number

247804734267

Result

✗ Failed

- Notice** Nail in nearside rear tyre
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Rear fog lamp not working (1.3.2b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Fail** Nearside Outer Front position lamp(s) not working (1.1.A.3b)
- Notice** N/s/r tyre worn around outer edge
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #9**

2013-05-29 12:06

MOT test number

535149543117

Result

✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #8

2013-05-28 17:17

MOT test number

196098043110

Result

✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7

2012-05-08 16:53

MOT test number

869469622150

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2011-04-20 13:40**MOT test number** 836780811130**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #5** 2011-04-19 10:59**MOT test number** 367409401138**Result** ✗ Failed**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Pass with rectification** Offside Headlamp aim too low (1.8)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #4** 2010-02-04 10:36**MOT test number** 362905230031**Result** ✓ Passed

**MOT #3** 2010-01-29 10:32**MOT test number** 474859620027**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2009-06-18 07:29**MOT test number** 720919069191**Result** ✓ Passed**MOT #1** 2008-06-03 10:53**MOT test number** 974285658161**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	EF54LFM
Plate since	2019-09-29
Current registration	EF54LFM
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2005-01-18
Last registration	2023-08-15
Complete history	See info



Registration #1	2005-01-18	13 mi
Registration #2	2008-06-03	45.153 mi
Registration #3	2009-06-18	55.692 mi
Registration #4	2010-01-29	62.419 mi
Registration #5	2010-02-04	62.426 mi
Registration #6	2011-04-19	66.303 mi
Registration #7	2011-04-20	66.303 mi
Registration #8	2012-05-08	71.577 mi
Registration #9	2013-05-28	78.827 mi
Registration #10	2013-05-29	78.836 mi
Registration #11	2014-08-22	92.310 mi
Registration #12	2014-08-22	92.310 mi
Registration #13	2015-08-13	100.601 mi
Registration #14	2016-05-20	111.277 mi
Registration #15	2016-05-20	111.277 mi
Registration #16	2016-05-20	111.277 mi
Registration #17	2016-05-20	111.277 mi
Registration #18	2016-05-20	111.277 mi
Registration #19	2016-05-20	111.277 mi
Registration #20	2016-05-20	111.277 mi
Registration #21	2016-05-20	111.277 mi
Registration #22	2016-05-20	111.277 mi
Registration #23	2016-05-20	111.277 mi
Registration #24	2016-05-20	111.277 mi
Registration #25	2016-05-20	111.277 mi



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Max. allowed weight	2735 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	267835
---------------	--------