





report date: 2022-08-09

General information

Make	MASERATI
Model	COUPE V8 GRANSPORT
Colour	Black
Year of manufacture	2005
Top speed	180 mph
0 - 60 mph	4.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	395 BHP
Max. torque	452 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.8 mpg
Consumption extra urban	22.6 mpg
Consumption combined	16.1 mpg
CO2 emission	400 g/km
CO2 label	М



CarCheck.co.uk page 1/14



RX55FRU

report date: 2022-08-09


Internet history

Entry 1


Date 2022-01-25

Pictures 30

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

Advice

MOT expiry date	2024-11-19
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	31
Total items failed	7

MOT #20	2023-11-20 15:03
MOT test number	763421262498
Result	✓ Passed
Next expiry date	2024-11-19

MOT #19	2022-09-22 10:57
MOT test number	943907536332
Result	√ Passed

MOT #18	2021-09-13 16:39
MOT test number	907807411685
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Lower arm/TCA (5.3.4 (a) (i))	
Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	

Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 3/14



MOT #17 2021-08-31 10:58

MOT test number 245140433525

Result X Failed

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing Inner edge tearing.. (5.2.3 (d) (ii))

Advice Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Fail Offside Headlamp aim too far to the right (4.1.2 (a))

Advice Handbrake has little reserve travel

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Lower arm/TCA (5.3.4 (a) (i))

Advice Nearside Front Tyre slightly damaged/cracking or perishing Inner edge tearing.. (5.2.3 (d) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))

Fail Nearside Headlamp aim too far to the right (4.1.2 (a))

MOT #16 2020-08-27 11:39

MOT test number 698421328179

Result J Passed

Advice Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



Result

RX55FRU report date: 2022-08-09

× Failed

MOT #15 2019-08-23 10:16

MOT test number 534487792368

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #14 2019-08-21 12:57

MOT test number 262000422541

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13 2017-10-31 12:41

MOT test number 623450966649

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit Tyre worn on inner edge (4.1.E.1)

MOT #12 2016-11-10 12:35

MOT test number 245813991037

Result ✓ Passed

MOT #11 2015-11-06 13:43

MOT test number 902191526577

Advice Offside rear tyre worn on inner edge

Advice 2 nails in nearside rear tyre

CarCheck.co.uk page 5/14



MOT #10 2015-11-03 09:35

MOT test number 639915448032

Result X Failed

Fail Offside Steering rack gaiter split (2.2.D.2d)

Advice Offside rear tyre worn on inner edge

Advice 2 nails in nearside rear tyre

MOT #9 2014-11-04 10:01

MOT test number 697508204324

Result
✓ Passed

MOT #8 2013-10-25 14:15

MOT test number 405218293222

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2012-10-23 09:07

MOT test number 506207992295

Result
✓ Passed

MOT #6 2011-10-27 12:16

MOT test number 195270601353

Result ✓ Passed

MOT #5 2011-10-25 09:29

MOT test number 867038891264

Result X Failed

Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 6/14



MOT #4 2010-10-21 09:57

MOT test number 342544390266

Result
✓ Passed

MOT #3 2009-10-27 17:34

MOT test number 272360309307

Result
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #2 2009-10-22 11:52

MOT test number 534845399228

Result X Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #1 2008-09-20 08:50

MOT test number 942024668241

Result ✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 February
Days left	288
MOT expiry date	19 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MASERATI salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history	
For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Download here.	

	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-09-29
Last registration	2023-11-20
Complete history	See info



Registration #1	2005-09-29	12 mi
Registration #2	2008-09-20	9.079 mi
Registration #3	2009-10-22	14.758 mi
Registration #4	2009-10-27	14.778 mi
Registration #5	2010-10-21	17.010 mi
Registration #6	2011-10-25	20.208 mi
Registration #7	2011-10-27	20.208 mi
Registration #8	2012-10-23	22.797 mi
Registration #9	2013-10-25	25.182 mi
Registration #10	2014-11-04	27.100 mi
Registration #11	2015-11-03	29.318 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.177 es
Registration #15		11.777 es
Registration #16		11.177 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		0.00 44

More info >

CarCheck.co.uk page 13/14



		_		
- 11	manciai	חר ג.	MOIG	nt.
	mensioı	אט כוו	welu	III.

Width	1822 mm
Height	1295 mm
Length	4523 mm
Wheel base	2660 mm
Kerb weight	1680 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	97975

CarCheck.co.uk page 14/14