



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY TITANIUM
Colour	Blue
Year of manufacture	2010
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-08-04
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-15
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	51
Total items failed	2

MOT #15	2023-11-16 10:46
MOT test number	125064530969
Result	✓ Passed
Next expiry date	2024-11-15
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #14	2023-11-15 16:39
MOT test number	751881148159
Result	✗ Failed
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)
DANGEROUS	Offside Steering arm deformed to the extent that steering is affected (2.1.3 (c) (ii))
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13** 2022-10-05 16:07**MOT test number** 972181482941**Result** ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Central Front Shock absorbers has light misting of oil both front (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2021-10-29 14:42**MOT test number** 471322280522**Result** ✓ Passed**MOT #11** 2020-09-29 15:13**MOT test number** 996032105773**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #10**

2020-09-28 14:56

MOT test number

106010621465

Result**✗ Failed**

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9

2019-09-24 11:15

MOT test number

628457959120

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2019-09-18 09:17**MOT test number** 834898631161**Result** ✗ Failed**MAJOR** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Side repeater missing (4.4.1 (a) (ii))**MOT #7** 2018-09-19 11:37**MOT test number** 416802950298**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear heat shield loose

**MOT #6** 2017-09-18 12:18**MOT test number** 654415287585**Result** ✓ Passed**Advice** Offside Rear tyre starting to wear inner edge**Advice** Play in steering rack inner joint(s)**MOT #5** 2017-01-25 10:45**MOT test number** 873554391434**Result** ✓ Passed**Advice** Uneven wear nearside rear tyre**MOT #4** 2016-01-26 10:44**MOT test number** 233648168953**Result** ✓ Passed**MOT #3** 2014-10-06 10:58**MOT test number** 158669774294**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Offside front tyre worn on inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-10-10 14:46**MOT test number** 318953683235**Result** ✓ Passed



MOT #1	2013-10-09 11:54
MOT test number	767202083243
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Uneven wear both front an rear tyres
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK60JNO
Plate since	2019-03-29
Current registration	EK60JNO
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-08
Last registration	2023-11-16
Complete history	See info



Registration #1	2010-10-08	29 mi
Registration #2	2013-10-09	34.006 mi
Registration #3	2013-10-10	34.006 mi
Registration #4	2014-10-06	45.526 mi
Registration #5	2016-01-26	62.244 mi
Registration #6	2017-01-25	77.920 mi
Registration #7	2017-09-18	83.847 mi
Registration #8	2018-09-19	107.602 mi
Registration #9	2019-09-18	128.510 mi
Registration #10	2020-09-18	151.377 mi
Registration #11	2021-09-18	174.244 mi
Registration #12	2022-09-18	197.111 mi
Registration #13	2023-09-18	220.000 mi
Registration #14	2024-03-29	242.889 mi
Registration #15	2024-03-29	265.778 mi
Registration #16	2024-03-29	288.667 mi
Registration #17	2024-03-29	311.556 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AU29117