





report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 280
Colour	Silver
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	300 Nm at 3.500 rpm
Engine capacity	2.996 сс
Cylinders	6
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	38.2 mpg
Consumption combined	29.7 mpg
CO2 emission	222 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-20

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-06-27
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	10
Total items failed	5

MOT #16	2023-06-28 09:34
MOT test number	765231139076
Result	✓ Passed
Next expiry date	2024-06-27

MOT #15	2023-06-27 15:38
MOT test number	308705093078
Result	× Failed
DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge replace now (5.2.3 (e))	

MOT #14		2022-06-23 10:05
MOT test	number	932598033628
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		(5.2.3 (d) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #13		2022-06-23 09:16
MOT test	number	969957638244
Result		× Failed
MAJOR	Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		(5.2.3 (d) (i))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #12		2020-11-19 14:38
MOT test number		887087709039
Result		✓ Passed
MOT #11		2014-08-05 17:34
MOT test number		317657614499
Result		🗙 Failed
Pass with rectification	Nearside Front Headlamp not working on main beam (1.7.5a)	
Pass with rectification	Front passenger door does not latch securely closed (6.2.B.1a)	

Pass with rectification	From passenger door does not laten securely closed (6.2.b.1a)	
MOT #10		2014-08-05 17:34
MOT test number		335627514455
Result		✓ Passed
MOT #9		2013-08-23 09:13
MOT test number		478745933231
Result		✓ Passed
MOT #8		2012-09-01 10:28
MOT test number		736155942299
Result		✓ Passed

CarCheck.co.uk page 4/12



Result

LM05PYW

report date: 2024-03-28

✓ Passed

MOT test number 26 Result	5040672169
Result	
	✓ Passed
MOT #6 2011	-06-22 12:47
MOT test number 96	7863271140
Result	✓ Passed
MOT #5 2011	-06-22 10:02
MOT test number 83	6913171177
Result	🗙 Failed
Notice Tear in nearside front tyre wall	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

MOT #4	2010-06-28 15:11
MOT test number	223459070190
Result	✓ Passed
MOT #3	2009-06-23 13:50
MOT test number	292284179468
Result	✓ Passed
MOT #2	2008-06-11 14:28
MOT test number	263513468479

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #1

MOT test number

610663968133

Result

Pass with rectification

Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		history
- 11	Nner	INISTAK

e when misterly	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downledone.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	SIK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2005-07-21
Last registration	2023-06-28
Complete history	See info



Registration #1	2005-07-21	11 mi
Registration #2	2008-06-11	12.941 mi
Registration #3	2009-06-23	17.760 mi
Registration #4	2010-06-28	22.520 mi
Registration #5	2011-06-22	26.779 mi
Registration #6	2011-06-22	26.779 mi
Registration #7	2012-06-18	30.383 mi
Registration #8	2012-09-01	31.583 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



report date: 2024-03-28

			_		
- 11	manc	Innc	λ.	MOL	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1460 kg
Max. allowed weight	1755 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27294230116675

CarCheck.co.uk page 12/12