



report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Red
Year of manufacture	2010
Top speed	160 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2022-02-19
Pictures	19
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-23
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	7

MOT #16	2024-02-24 08:34
MOT test number	531135453190
Result	✓ Passed
Next expiry date	2025-02-23

MOT #15	2023-02-18 08:06
MOT test number	473228487634
Result	✓ Passed

MOT #14	2023-02-17 15:21
MOT test number	412812158817
Result	✗ Failed
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #13	2022-02-22 14:31
MOT test number	670931689348
Result	✓ Passed
Advice	Offside Front Nail in tyre

**MOT #12** 2021-07-22 07:41**MOT test number** 973744963453**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm and worn outer edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 4-3mm and worn on outer edge (5.2.3 (e))**MOT #11** 2020-07-20 08:14**MOT test number** 988454271646**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))**MOT #10** 2019-04-16 09:16**MOT test number** 921544853397**Result** ✓ Passed**MOT #9** 2018-04-14 07:23**MOT test number** 618855108037**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2017-04-22 10:04**MOT test number** 888208159403**Result** ✓ Passed

**MOT #7** 2017-04-08 07:34**MOT test number** 344820972944**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2016-04-27 14:02**MOT test number** 598433919669**Result** ✓ Passed**MOT #5** 2016-04-25 16:22**MOT test number** 312936436234**Result** ✗ Failed**Fail** Nearside Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #4** 2015-09-11 08:41**MOT test number** 641083850159**Result** ✓ Passed**Advice** Nearside Front Slight cracking in rear suspension arm bush**Advice** Offside Front Tyre worn close to the legal limit 2mm on stepped edge (4.1.E.1)

**MOT #3** 2015-09-11 08:41**MOT test number** 271474369535**Result** ✗ Failed**Advice** Nearside Front Slight cracking in rear suspension arm bush**Advice** Offside Front Tyre worn close to the legal limit 2mm on stepped edge (4.1.E.1)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-09-12 10:44**MOT test number** 819125454252**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-09-16 11:06**MOT test number** 347609253443**Result** ✓ Passed**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
23 February 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	23 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>WJ10XRV</b>
Plate since	2019-09-29
Current registration	<b>WJ10XRV</b>
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-29
Last registration	2024-02-24
Complete history	<a href="#">See info</a>



Registration #1	2010-04-29	27 mi
Registration #2	2013-09-16	30.384 mi
Registration #3	2014-09-12	39.277 mi
Registration #4	2015-09-11	48.902 mi
Registration #5	2015-09-11	48.902 mi
Registration #6	2016-04-25	56.193 mi
Registration #7	2016-04-27	56.193 mi
Registration #8	2017-04-08	60.625 mi
Registration #9	2017-04-22	60.733 mi
Registration #10	2017-05-01	60.733 mi
Registration #11	2017-05-01	60.733 mi
Registration #12	2017-05-01	60.733 mi
Registration #13	2017-05-01	60.733 mi
Registration #14	2017-05-01	60.733 mi
Registration #15	2017-05-01	60.733 mi
Registration #16	2017-05-01	60.733 mi
Registration #17	2017-05-01	60.733 mi
Registration #18	2017-05-01	60.733 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1860 mm
Height	1451 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1563 kg
Max. allowed weight	2156 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DYWS4017889