





report date: 2022-08-13

General information

Make	MASERATI
Model	GRANSPORT V8
Colour	Blue
Year of manufacture	2007
Top speed	180 mph
0 - 60 mph	4.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	395 BHP
Max. torque	452 Nm at 4.500 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	10.8 mpg
Consumption extra urban	22.6 mpg
Consumption combined	16.1 mpg
CO2 emission	400 g/km
CO2 label	M



CarCheck.co.uk page 1/15



Internet history

Entry 1

Date 2022-06-13

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2024-10-10
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	39
Total items failed	6

MOT #17	2023-10-11 12:24
MOT test number	313293196652
Result	✓ Passed
Next expiry date	2024-10-10
Advice Front Brake disc worn, pitted or scored, but not seriously weakene (ii))	ed poor / n/s grooved (1.1.14 (a)
Advice Offside Rear handbrake effort low	

MOT #16	2022-06-10 09:4
MOT test number	34686794053
Result	✓ Passe
Advice Front Brake disc	worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))

MOT #15		2021-10-27 15:20
MOT test	number	116766179592
Result		✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened All for	ur (1.1.14 (a) (ii))

CarCheck.co.uk page 3/15



MOT #14 2021-10-25 10:56

MOT test number 318034512397

Result X Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened All four (1.1.14 (a) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))

MOT #13 2020-09-30 07:52

MOT test number 494608188866

Result

Passed

Advice Offside Front tyre worn and perished on inner edge

Advice Front brake discs corroded

MOT #12 2019-06-15 09:18

MOT test number 909680165222

Result

Passed

Advice Offside Front Tyre worn unevenly on inner edge

Advice Brake disc worn, pitted or scored, but not seriously weakened both fronts corroded/pitted on inner

face (1.1.14 (a) (ii))

CarCheck.co.uk page 4/15



MOT #11

LJO7EZR report date: 2022-08-13

2018-06-20 09:38

MOT test number 302958800928

Result ✓ Passed Advice Offside front wheel has been welded repaired on inner bead Advice Slight oil leak from both rear top covers Advice Nearside rear tyre valve cap/sleeve missing Advice Front Direction indicator slightly discoloured both (4.4.3 (a)) Advice Offside front tyre bald on inner edge + slightly wearing on outer edge Advice Nearside side repeater lens condensated Nearside front brake disc slightly corroded on inner face Advice **Advice** Nearside front tyre wearing on inner edge + slightly wearing on outer edge

CarCheck.co.uk page 5/15



LJO7EZR

MOT #10 2018-06-18 11:33

MOT test number 274175380962

Result X Failed

Minor Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Offside front wheel has been welded repaired on inner bead

Advice Slight oil leak from both rear top covers

Fail Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Nearside rear tyre valve cap/sleeve missing

Advice Offside front tyre bald on inner edge + slightly wearing on outer edge

Advice Nearside side repeater lens condensated

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))

Advice Nearside front brake disc slightly corroded on inner face

Advice Front Direction indicator slightly discoloured both (4.4.3 (a))

Advice Nearside front tyre wearing on inner edge + slightly wearing on outer edge

MOT #9 2017-05-03 08:16

MOT test number 314845729630

Result \(\sqrt{Passed} \)

Advice Offside rear tyre on 3mm

Advice Front Direction indicator slightly discoloured both (1.4.A.2f)

Advice Offside front wheel inner rim has been welded

Advice Offside front headlight aim on lowest limit

CarCheck.co.uk page 6/15



MOT #8 2016-05-06 08:48

MOT test number 365956003665

Result
✓ Passed

Advice Both wiper blades split but clearing screen

Advice Fuel lines and brake pipes secure but clips not correctly fastened.

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-05-08 16:53

MOT test number 569828725183

Result ✓ Passed

Notice Offside rear tyre has small cracks in inner sidewall no cords visible.

Notice Nail in nearside rear tyre

Notice Nearside front tyre has shoulderd wear.

MOT #6 2014-05-08 07:51

MOT test number 708828124169

Result
✓ Passed

Advice Offside Front Upper Suspension arm has slight play in a pin/bush (2.4.G.2)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #5 2013-05-09 17:00

MOT test number 765579823141

CarCheck.co.uk page 7/15



MOT #4

MOT test number

Fail

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #3
 2012-05-05 09:31

 MOT test number
 148856222116

 Result
 ✓ Passed

 MOT #2
 2012-04-27 15:57

 MOT test number
 799158012107

 Result
 X Failed

 Fail
 Nearside Front Steering rack gaiter split (2.2.D.2d)

MOT #1	2011-01-20 09:25
MOT test number	597270421038
Result	✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check



Tax status	Valid until 1 November
Days left	195
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 9/15



Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.


Damage 1

Date	
Category	
Туре	

Damage 2

Date		
Category		

Type



Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Owner history

o milet mater y			
		ave this MASERATI? How many o see all owner registrations. Dow	

Plate changes			More info >
See in this check if this MA	ASERATI had different numb	per plates.	
Number of plates			,
Current registration			SK UK
Plate since			
Current registration			NK SIE
Plate since			
			More info >

CarCheck.co.uk page 12/15



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-05-21
Last registration	2023-10-11
Complete history	See info



Registration #1	2007-05-21	8 mi
Registration #2	2011-01-20	15.053 mi
Registration #3	2012-04-27	16.185 mi
Registration #4	2012-05-05	16.189 mi
Registration #5	2013-05-09	21.044 mi
Registration #6	2013-05-09	21.044 mi
Registration #7	2014-05-08	26.758 mi
Registration #8	2015-05-08	32.408 mi
Registration #9	2016-05-06	38.705 mi
Registration #10	2017-05-03	42.484 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 esi
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		D.377 es

More info >

CarCheck.co.uk page 14/15



Dimensions & weight

Width	1822 mm
Height	1295 mm
Length	4523 mm
Wheel base	2660 mm
Kerb weight	1680 kg

Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Engine number	113391

CarCheck.co.uk page 15/15