




report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Grey
Year of manufacture	2010
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	146 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G





MOT history

MOT expiry date	2024-08-04
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	12

MOT #18	2023-07-31 11:24
MOT test number	622998530019
Result	✓ Passed
Next expiry date	2024-08-04

MOT #17	2022-08-05 13:49
MOT test number	778295458779
Result	✓ Passed

MOT #16	2022-08-05 11:33
MOT test number	819852563632
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2021-05-10 12:35
MOT test number	219210262344
Result	✓ Passed

**MOT #14**

2020-09-23 15:50

MOT test number

796805759521

Result

✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Hydraulic leak, but not excessive from the steering rack (8.4.1 (a) (i))**MOT #13**

2020-09-23 10:36

MOT test number

598705947110

Result

✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Hydraulic leak, but not excessive from the steering rack (8.4.1 (a) (i))**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12**

2019-09-17 07:56

MOT test number

379304299181

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))

**MOT #11** 2018-09-13 09:34**MOT test number** 531253574043**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-09-13 08:31**MOT test number** 470728494704**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #9** 2017-09-25 08:39**MOT test number** 529392445067**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #8** 2016-09-27 07:30**MOT test number** 954408671828**Result** ✓ Passed**Advice** Offside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2016-09-22 15:44**MOT test number** 287313821342**Result** ✗ Failed**Fail** Offside Front Steering rack gaiter insecure (2.2.D.2d)**Advice** Offside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #6** 2016-02-12 12:35**MOT test number** 711750154609**Result** ✓ Passed**MOT #5** 2016-02-12 10:20**MOT test number** 904688079296**Result** ✗ Failed**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #4** 2015-02-16 09:42**MOT test number** 708167045077**Result** ✓ Passed**MOT #3** 2014-02-19 14:11**MOT test number** 947030454082**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2014-02-19 11:20
MOT test number	637380854079
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #1	2013-02-20 12:22
MOT test number	446731253065
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Notice	Vehicle's internal headlight adjuster altered to recheck lights



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
4 August 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-02-25
Last registration	2023-07-31
Complete history	See info



Registration #1	2010-02-25	20 mi
Registration #2	2013-02-20	18.755 mi
Registration #3	2014-02-19	24.316 mi
Registration #4	2014-02-19	24.316 mi
Registration #5	2015-02-16	29.693 mi
Registration #6	2016-02-12	34.998 mi
Registration #7	2016-02-12	34.998 mi
Registration #8	2016-09-22	39.578 mi
Registration #9	2016-09-27	39.578 mi
Registration #10	2017-09-25	49.707 mi
Registration #11	2018-09-25	59.836 mi
Registration #12	2019-09-25	69.965 mi
Registration #13	2020-09-25	80.094 mi
Registration #14	2021-09-25	90.223 mi
Registration #15	2022-09-25	100.352 mi
Registration #16	2023-07-31	110.481 mi
Registration #17	2023-07-31	110.481 mi
Registration #18	2023-07-31	110.481 mi
Registration #19	2023-07-31	110.481 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AL39191