





report date: 2024-03-29

### General information

Make	VOLKSWAGEN
Model	POLO MATCH (80BHP)
Colour	Red
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	80 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-17

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

Advice

MOT expiry date	2024-08-20
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #15	2023-08-21 14:10
MOT test number	701773906967
Result	✓ Passed
Next expiry date	2024-08-20
Advice Nearside Front Outer Drive shaft flexible coupling slightly deteriorated (6.1.7 (d)	(i))

MOT #14	2022-07-25 10:10
MOT test number	529547918730
Result	✓ Passed
MOT #13	2021-07-27 12:57
MOT test number	929964875410
Result	✓ Passed
MOT #12	2020-11-19 14:14
MOT test number	277046998196
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #11** 2020-11-19 11:29 **MOT** test number 416447349217 Result × Failed **Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Fail Brake lever has insufficient reserve travel (1.1.2 (a)) Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail Fail Offside Front Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Minor
(i))

Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9

MOT test number

742298439293

Result

Advice Covers on floor

Advice Exhaust back box peeling

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #8		2017-06-06 08:49
MOT test	number	506614245238
Result		✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Plastic covers on floors and engine	
Advice	Outer skin on back box corroding	

MOT #7	2016-06-07 15:02
MOT test number	772236110021
Result	✓ Passed
MOT #6	2016-06-06 11:28
MOT test number	719543795886
Result	<b>X</b> Failed
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Fail Parking brake lever has no reserve travel (3.1.6b)	

MOT #5	2015-06-11 15:28
MOT test number	147712665115
Result	✓ Passed

MOT #4	2014-09-11 15:19
MOT test number	817334354291
Result	✓ Passed

MOT #3	2013-09-1/ 10:16
MOT test number	489870063287
Result	✓ Passed

CarCheck.co.uk page 5/13



 MOT #2
 2012-09-06 13:53

 MOT test number
 617560852273

 Result
 ✓ Passed

 MOT #1
 2011-09-22 10:25

 MOT test number
 498025361279

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	20 August 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
********	
***************************************	
***************************************	
*********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	AIS UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-30
Last registration	2023-08-21
Complete history	See info



Registration #1	2008-10-30	27 mi
Registration #2	2011-09-22	11.061 mi
Registration #3	2012-09-06	13.556 mi
Registration #4	2013-09-17	16.333 mi
Registration #5	2014-09-11	19.068 mi
Registration #6	2015-06-11	21.010 mi
Registration #7	2016-06-06	27.274 mi
Registration #8	2016-06-07	27.292 mi
Registration #9	2017-06-06	35.811 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		71.777 esi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

	m report.
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Max. allowed weight	1580 kg

## Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 13/13

Number of axles	2

BUD538829

**Engine number**