





report date: 2024-03-29

General information

Make	AUDI
Model	A3 MPI SE
Colour	White
Year of manufacture	2008
Top speed	115 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	148 Nm at 3.800 rpm
Engine capacity	1.595 сс
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	41.5 mpg
CO2 emission	162 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-28


Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

2021-06-14

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-05-01
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	4

MOT #18	2023-05-02 06:22
MOT test number	774322582037
Result	✓ Passed
Next expiry date	2024-05-01

MOT #17	2023-04-28 07:47

MOT test number 330159283103

Result

X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MAJOR Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MAJOR Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #16	2022-03-23 15:01
MOT test number	152456862139
Result	✓ Passed

CarCheck.co.uk page 3/13



Result

MX58WVE

report date: 2024-03-29

✓ Passed

MOT #15 2022-03-23 10:57

MOT test number 267665463337

Result X Failed

MAJOR Nearside Headlamp aim too far to the right (4.1.2 (a))

MOT #14 2021-03-26 13:31

MOT test number 844779647860

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Shock absorbers has a slightly worn bush Internal bush (5.3.2 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Both front shockers corroded

Advice Nearside Front Play in steering rack inner joint(s)

MOT #13 2021-03-26 10:16

MOT test number 476198606724

Result × Failed

Advice Both front shockers corroded

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Front Play in steering rack inner joint(s)

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Shock absorbers has a slightly worn bush Internal bush (5.3.2 (c))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt SPLIT (6.1.7 (g) (ii))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #12 2020-01-29 12:46

MOT test number 415556891408

Result \rightarrow Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11 2019-01-30 12:01

MOT test number 845274537007

MOT #10 2019-01-29 17:18

MOT test number 630014337724

Result X Failed

MAJOR Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9 2018-01-24 11:18

MOT test number 144596378144

Result ✓ Passed

MOT #8 2018-01-23 12:03

MOT test number 219558375717

Result X Failed

Fail Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2017-01-25 09:41

MOT test number 912764886009

Result
✓ Passed

CarCheck.co.uk page 5/13



Result

MX58WVE

report date: 2024-03-29

× Failed

MOT #6 2015-12-09 09:35

MOT test number 538984763159

Result \rightarrow Passed

MOT #5 2014-11-21 09:22

MOT test number 677745324308

Result Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-11-15 15:58

MOT test number 959769013342

Result \rightarrow Passed

MOT #3 2012-10-05 12:47

MOT test number 246589972226

MOT #2 2012-10-05 12:47

MOT test number 306929272251

Pass with rectification Offside Headlamp aim too far to the right (1.8)

Pass with rectification Nearside Headlamp aim too far to the right (1.8)

MOT #1 2011-09-05 10:37

MOT test number 265958441282

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	1 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



MX58WVE report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

*		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report I		ve?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-01
Last registration	2023-05-02
Complete history	See info



2008-09-01	10 mi
2011-09-05	39.985 mi
2012-10-05	46.953 mi
2013-11-15	52.960 mi
2014-11-21	59.291 mi
2015-12-09	66.812 mi
2017-01-25	75.253 mi
2018-01-23	81.654 mi
2018-01-24	81.656 mi
2010 01 20	86.267 mi
2019-01-29	00.207 1111
2013-01-23	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	00.207 1111
	2011-09-05 2012-10-05 2013-11-15 2014-11-21 2015-12-09 2017-01-25 2018-01-23

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1421 mm
Length	4238 mm
Wheel base	2578 mm
Kerb weight	1185 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number BSE 705739