



report date: 2024-03-29

General information

Make	VOLVO
Model	S40 E4 D SE V50
Colour	Silver
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-06
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #20</b>	2021-07-26 13:56
<b>MOT test number</b>	425628283741
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-07-25

<b>MOT #19</b>	2021-03-02 16:19
<b>MOT test number</b>	690067512338
<b>Result</b>	✓ Passed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #18</b>	2021-03-02 14:09
<b>MOT test number</b>	967361285746
<b>Result</b>	✗ Failed

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #17</b>	2020-03-19 10:26
<b>MOT test number</b>	310013766913
<b>Result</b>	✓ Passed

<b>MOT #16</b>	2020-03-13 14:20
<b>MOT test number</b>	409501562497
<b>Result</b>	✗ Failed

**Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Nearside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #15	2020-03-13 14:16
MOT test number	155331609715
Result	✓ Passed
MOT #14	2019-03-08 09:17
MOT test number	427568629922
Result	✓ Passed
MOT #13	2018-03-09 09:05
MOT test number	613451681210
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #12	2017-03-15 18:40
MOT test number	322063882941
Result	✓ Passed



MOT #11

2017-01-17 13:42

MOT test number

425991521006

Result		✗ Failed
Fail	Registration plate lamp not working one bulb (1.1.C.1d)	
Fail	Offside Front coil spring broken (2.4.C.1a)	
Fail	Fuel system component leaking injector area (7.2.3)	
Advice	Exhaust heat shield adrift	
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)	
Fail	Nearside Front coil spring broken (2.4.C.1a)	
Fail	Nearside Front Shock absorber has a serious fluid leak (2.7.3)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Advice	Silencer box outer skin adrift	

**MOT #10**

2016-09-08 08:53

**MOT test number**

156796682219

**Result**

✗ Failed

- Fail** Nearside Front Headlamp aim too low (1.8)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)
- Fail** Offside Front front brake excessively fluctuating (3.7.B.3)
- Advice** Engine covers and under trays fitted obscuring some omponents
- Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside Rear rear brake recording little or no effort (3.7.B.5a)

**MOT #9**

2016-04-14 18:20

**MOT test number**

778351407622

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)

**MOT #8**

2016-04-12 09:35

**MOT test number**

678575464271

**Result**

✗ Failed

**Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement REAR OF FRONT (2.4.G.2)

**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)

**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement REAR OF FRONT (2.4.G.2)

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Nearside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)

**MOT #7**

2015-04-21 15:10

**MOT test number**

557581615133

**Result**

✓ Passed

**MOT #6**

2014-04-23 16:26

**MOT test number**

548193614108

**Result**

✓ Passed

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2013-04-19 15:36

**MOT test number**

886159003194

**Result**

✓ Passed

**MOT #4**

2012-11-02 08:59

**MOT test number**

958067502338

**Result**

✓ Passed



MOT #3	2011-09-23 13:09
MOT test number	369686761202
Result	✓ Passed
MOT #2	2010-09-23 11:20
MOT test number	252196860241
Result	✓ Passed
MOT #1	2009-09-22 11:47
MOT test number	851015069227
Result	✓ Passed





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-28
Last registration	2021-07-26
Complete history	<a href="#">See info</a>



Registration #1	2006-09-28	8 mi
Registration #2	2009-09-22	23.691 mi
Registration #3	2010-09-23	32.444 mi
Registration #4	2011-09-23	35.568 mi
Registration #5	2012-11-02	41.268 mi
Registration #6	2013-04-19	42.412 mi
Registration #7	2014-04-23	56.068 mi
Registration #8	2015-04-21	60.765 mi
Registration #9	2016-04-12	88.939 mi
Registration #10	2016-04-14	88.940 mi
Registration #11	2016-09-08	96.420 mi
Registration #12	2016-09-08	96.420 mi
Registration #13	2016-09-08	96.420 mi
Registration #14	2016-09-08	96.420 mi
Registration #15	2016-09-08	96.420 mi
Registration #16	2016-09-08	96.420 mi
Registration #17	2016-09-08	96.420 mi
Registration #18	2016-09-08	96.420 mi
Registration #19	2016-09-08	96.420 mi
Registration #20	2016-09-08	96.420 mi
Registration #21	2016-09-08	96.420 mi
Registration #22	2016-09-08	96.420 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4014833