



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Red
Year of manufacture	2014
Top speed	151 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-07
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	12
Total items failed	3

**MOT #13** 2023-08-23 12:58

**MOT test number** 521652106422

**Result** ✓ Passed

**Next expiry date** 2024-08-22

**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #12** 2023-08-23 12:58

**MOT test number** 653805816408

**Result** ✗ Failed

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2022-07-26 13:13

**MOT test number** 612335974127

**Result** ✓ Passed



<b>MOT #10</b>	2022-07-25 11:46
<b>MOT test number</b>	932906700909
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
<b>MAJOR</b>	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
<b>DANGEROUS</b>	Nearside Front Lower Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))

<b>MOT #9</b>	2021-08-11 13:32
<b>MOT test number</b>	292017968200
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2021-02-19 13:54
<b>MOT test number</b>	202800188267
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2020-05-27 11:09
<b>MOT test number</b>	802235389415
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #6</b>	2019-05-08 08:59
<b>MOT test number</b>	933278878515
<b>Result</b>	✓ Passed



<b>MOT #5</b>	2019-05-08 07:59
<b>MOT test number</b>	124823089876
<b>Result</b>	✗ Failed
<b>DANGEROUS</b>	Offside Front Valve stem seriously damaged (5.2.3 (j))
<b>DANGEROUS</b>	Nearside Front Valve stem seriously damaged (5.2.3 (j))
<b>MAJOR</b>	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
<b>DANGEROUS</b>	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

<b>MOT #4</b>	2018-05-15 10:20
<b>MOT test number</b>	538406071329
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2018-05-15 09:25
<b>MOT test number</b>	154304564507
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

<b>MOT #2</b>	2017-05-17 13:43
<b>MOT test number</b>	839698149126
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2017-05-17 13:43
<b>MOT test number</b>	409909988011
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Nearside Headlamp aim too low (1.8)



Tax & MOT check

**×**  
**Untaxed**

**Tax expired:**  
23 April 2024

**✓**  
**MOT**

**Expires:**  
22 August 2024

<b>Tax status</b>	Expired at 23 April 2024
<b>Days left</b>	6 days too late
<b>MOT expiry date</b>	22 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




**Damage history**

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Damage 2**

<b>Date</b>	
<b>Category</b>	
<b>Type</b>	



**Extra MERCEDES-BENZ salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	OY14NCC
Plate since	2014-03-28
Current registration	OY14NCC
Plate since	2014-03-28

More info >



**Finance check**

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	15
<b>First mileage registration</b>	2014-03-25
<b>Last registration</b>	2023-08-23
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2014-03-25	26 mi
<b>Registration #2</b>	2017-05-17	24.647 mi
<b>Registration #3</b>	2017-05-17	24.647 mi
<b>Registration #4</b>	2018-05-15	32.707 mi
<b>Registration #5</b>	2018-05-15	32.707 mi
<b>Registration #6</b>	2019-05-08	39.216 mi
<b>Registration #7</b>	2019-05-08	39.216 mi
<b>Registration #8</b>	2020-05-27	45.761 mi
<b>Registration #9</b>	2020-05-27	45.761 mi
<b>Registration #10</b>	2020-05-27	45.761 mi
<b>Registration #11</b>	2020-05-27	45.761 mi
<b>Registration #12</b>	2020-05-27	45.761 mi
<b>Registration #13</b>	2020-05-27	45.761 mi
<b>Registration #14</b>	2020-05-27	45.761 mi
<b>Registration #15</b>	2020-05-27	45.761 mi

[More info >](#)



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032265025