



report date: 2024-03-29

General information

Make	CITROEN
Model	C-CROSSER HDI EXCLUSIVE
Colour	Black
Year of manufacture	2011
Top speed	123 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	380 Nm at 2.000 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	38.7 mpg
CO2 emission	192 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-08
Pictures	22
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-06-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	3

MOT #13	2023-06-02 09:51
MOT test number	495617545765
Result	✓ Passed
Next expiry date	2024-06-10

MOT #12	2022-06-11 06:56
MOT test number	408892124471
Result	✓ Passed

MOT #11	2022-06-11 06:56
MOT test number	891626508319
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10	2021-06-11 12:16
MOT test number	562874307095
Result	✓ Passed
Minor	Nearside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2020-10-05 15:21

**MOT test number**

292768136305

**Result**

✓ Passed

**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Spare wheel carrier loose**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Rear brake discs corroded**Advice** Spare tyre defective flat**MOT #8**

2020-10-05 11:17

**MOT test number**

293222176512

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge heavily perished, cuts (5.2.3 (e))**Advice** Spare wheel carrier loose**Advice** Spare tyre defective flat**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**DANGEROUS** Offside Rear Tyre has ply or cords exposed through perishing (5.2.3 (d) (ii))**Advice** Rear brake discs corroded**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #7**

2019-04-02 12:17

**MOT test number**

342074444202

**Result**

✓ Passed

**Advice** Spare tyre underinflated**Advice** Rear tyres perished slightly**Advice** Rear brake discs slightly corroded

**MOT #6** 2018-03-20 13:46**MOT test number** 649476959520**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2018-03-20 13:46**MOT test number** 646245020328**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2017-03-02 15:26**MOT test number** 381577749951**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-12-22 15:21**MOT test number** 771760696557**Result** ✓ Passed**MOT #2** 2014-12-17 16:20**MOT test number** 627141354351**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #1	2014-01-16 10:16
MOT test number	245056814089
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
10 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	10 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-01-10
Last registration	2023-06-02
Complete history	<a href="#">See info</a>



Registration #1	2011-01-10	16 mi
Registration #2	2014-01-16	30.896 mi
Registration #3	2014-12-17	38.769 mi
Registration #4	2015-12-22	48.341 mi
Registration #5	2017-03-02	58.616 mi
Registration #6	2018-03-20	66.028 mi
Registration #7	2018-03-20	66.028 mi
Registration #8	2019-04-02	70.192 mi
Registration #9	2019-04-02	70.192 mi
Registration #10	2019-04-02	70.192 mi
Registration #11	2019-04-02	70.192 mi
Registration #12	2019-04-02	70.192 mi
Registration #13	2019-04-02	70.192 mi
Registration #14	2019-04-02	70.192 mi
Registration #15	2019-04-02	70.192 mi

More info >



Dimensions & weight

Width	1805 mm
Height	1715 mm
Length	4645 mm
Wheel base	2670 mm
Kerb weight	1715 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	DZ704005085