




report date: 2024-03-28

General information

Make	LAND ROVER
Model	FREELANDER TD4 XS
Colour	Green
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	11.7 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 150 BHP
Max. torque	420 Nm at 1.750 rpm
Engine capacity	2.179 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	50.4 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-09-10
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-16
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #14 2023-10-27 09:38

MOT test number 600326436280

Result ✓ Passed

Next expiry date 2024-11-16

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Towbar component corroded, but not excessively main crossmember and mounting surfaces (6.1.6 (a))
- Advice** Vehicle underside has various areas of surface corrosion
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all four brake discs (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive slight seepage from rear haldex unit, suspect core plug (8.4.1 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13 2022-11-04 15:53

MOT test number 681794882139

Result ✓ Passed

**MOT #12** 2022-11-03 12:49**MOT test number** 782235373222**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #11** 2021-11-17 10:25**MOT test number** 489852352682**Result** ✓ Passed**MOT #10** 2021-07-28 14:22**MOT test number** 122427340087**Result** ✓ Passed**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** General corrosion under vehicle**Advice** Offside Rear tyre slight cracking**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front windscreen wiper streaky**Advice** Nearside Front tyre outer edge wearing**MOT #9** 2020-07-28 14:36**MOT test number** 873141712972**Result** ✓ Passed**MOT #8** 2019-07-12 08:11**MOT test number** 324607452517**Result** ✓ Passed

**MOT #7** 2018-07-09 11:45**MOT test number** 379553564209**Result** ✓ Passed**MOT #6** 2017-06-30 15:55**MOT test number** 159365901744**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-07-05 16:28**MOT test number** 211908603312**Result** ✓ Passed**MOT #4** 2016-07-04 12:56**MOT test number** 851116060123**Result** ✗ Failed**Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #3** 2015-12-01 12:53**MOT test number** 203960994404**Result** ✓ Passed**MOT #2** 2014-10-24 12:25**MOT test number** 697687194201**Result** ✓ Passed



MOT #1	2014-04-08 14:07
MOT test number	739418194062
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
16 November 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	16 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	WU11HXK
Plate since	2019-09-29
Current registration	WU11HXK
Plate since	2019-09-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-01
Last registration	2023-10-27
Complete history	See info



Registration #1	2011-03-01	6 mi
Registration #2	2014-04-08	36.305 mi
Registration #3	2014-10-24	50.371 mi
Registration #4	2015-12-01	80.869 mi
Registration #5	2016-07-04	88.145 mi
Registration #6	2016-07-05	88.145 mi
Registration #7	2017-06-30	95.296 mi
Registration #8	2018-07-09	100.299 mi
Registration #9	2019-05-29	101.217 mi
Registration #10	2019-05-29	101.217 mi
Registration #11	2019-05-29	101.217 mi
Registration #12	2019-05-29	101.217 mi
Registration #13	2019-05-29	101.217 mi
Registration #14	2019-05-29	101.217 mi
Registration #15	2019-05-29	101.217 mi
Registration #16	2019-05-29	101.217 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2180 mm
Height	1740 mm
Length	4500 mm
Wheel base	2660 mm
Kerb weight	1770 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DZ794013534224DT