



TOYOTA

PK56FYL

report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA D-4D T3
Colour	Silver
Year of manufacture	-
Top speed	112 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	190 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	58.9 mpg





Internet history

Entry 1

Date	2021-10-19
Pictures	6
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #18	2024-01-17 15:22
MOT test number	510105788652
Result	✓ Passed
Next expiry date	2025-01-22
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front headlamps slightly clouded
Advice	Play in steering rack inner joint(s)
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Centre brake light inop.

MOT #17	2023-01-19 17:31
MOT test number	991744206042
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front headlamps slightly clouded

MOT #16	2022-01-18 17:22
MOT test number	272850153683
Result	✓ Passed
Advice	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15**

2021-01-23 12:54

MOT test number

373181755505

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill corroded (5.3.6 (a) (i))

Advice Rear axle corroded but not excessive

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive Inner sill corroded (5.3.6 (a) (i))

MOT #14

2019-12-04 14:58

MOT test number

624405406184

Result

✓ Passed

MOT #13

2018-12-22 15:45

MOT test number

190264755090

Result

✓ Passed

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Under body corroded

MOT #12

2018-12-20 17:40

MOT test number

197650010733

Result

✗ Failed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Under body corroded

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both sides (5.1.2 (b) (i))

Fail Nearside Front Suspension arm damaged and seriously weakened (5.3.3 (b) (i))

**MOT #11** 2017-12-22 14:33**MOT test number** 631177998960**Result** ✓ Passed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**MOT #10** 2017-12-22 12:32**MOT test number** 478256012616**Result** ✗ Failed**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**MOT #9** 2016-10-31 13:53**MOT test number** 794809053094**Result** ✓ Passed**MOT #8** 2016-10-30 13:28**MOT test number** 746187540860**Result** ✗ Failed**Fail** Offside Front Suspension arm corroded and seriously weakened (2.4.G.1)**MOT #7** 2015-10-10 14:12**MOT test number** 757638073215**Result** ✓ Passed**MOT #6** 2014-10-19 13:02**MOT test number** 328182294210**Result** ✓ Passed

**MOT #5** 2013-10-28 11:48**MOT test number** 437931003495**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-11-01 15:20**MOT test number** 367336402332**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-10-26 16:09**MOT test number** 758469591291**Result** ✓ Passed**Notice** Offside rear tyre wearing unevenly**Notice** Nail in nearside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-11-01 09:19**MOT test number** 933715400398**Result** ✓ Passed**Notice** Offside rear tyre small damage inner sidewall also starting to wear uneven**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2009-10-29 11:57**MOT test number** 343282709321**Result** ✓ Passed




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	PK56FYL
Plate since	2024-03-29
Current registration	PK56FYL
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-11-02
Last registration	2024-01-17
Complete history	See info



Registration #1	2006-11-02	10 mi
Registration #2	2009-10-29	30.494 mi
Registration #3	2010-11-01	40.200 mi
Registration #4	2011-10-26	44.159 mi
Registration #5	2012-11-01	46.256 mi
Registration #6	2013-10-28	49.062 mi
Registration #7	2014-10-19	52.242 mi
Registration #8	2015-10-10	56.010 mi
Registration #9	2016-10-30	61.015 mi
Registration #10	2016-10-31	61.015 mi
Registration #11	2016-10-31	61.015 mi
Registration #12	2016-10-31	61.015 mi
Registration #13	2016-10-31	61.015 mi
Registration #14	2016-10-31	61.015 mi
Registration #15	2016-10-31	61.015 mi
Registration #16	2016-10-31	61.015 mi
Registration #17	2016-10-31	61.015 mi
Registration #18	2016-10-31	61.015 mi
Registration #19	2016-10-31	61.015 mi
Registration #20	2016-10-31	61.015 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1190 kg
Max. allowed weight	1695 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1ND0319371