



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI SE
Colour	Black
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.999 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.6 mpg
Consumption extra urban	33.2 mpg
Consumption combined	26.4 mpg
CO2 emission	287 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-07-21
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-06
MOT pass rate	94 %
MOT passed	16
Failed MOT tests	1
Total advice items	21
Total items failed	1

## MOT #17 2023-08-07 13:13

MOT test number 244161318552

Result ✓ Passed

Next expiry date 2024-08-06

**Advice** Front Inner Steering linkage ball joint has slight play both rack knuckles (2.1.3 (b) (i))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake hose slightly deteriorated both sides (1.1.12 (b) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

## MOT #16 2022-08-05 07:45

MOT test number 686441153316

Result ✓ Passed**Advice** Front tyres scrubbed**Advice** Child Seat fitted not allowing full inspection of adult belt 2 at rear**Advice** Front Steering linkage ball joint has slight play both inner rack joints (2.1.3 (b) (i))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15** 2022-08-05 07:45**MOT test number** 171314018549**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front tyres scrubbed**Advice** Child Seat fitted not allowing full inspection of adult belt 2 at rear**Advice** Front Steering linkage ball joint has slight play both inner rack joints (2.1.3 (b) (ii))**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14** 2021-08-03 10:36**MOT test number** 690451829451**Result** ✓ Passed**MOT #13** 2021-06-28 11:11**MOT test number** 966047971186**Result** ✓ Passed**MOT #12** 2020-10-05 08:38**MOT test number** 365539956775**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**MOT #11** 2019-10-01 08:10**MOT test number** 197623778460**Result** ✓ Passed

**MOT #10** 2018-09-20 12:59**MOT test number** 447974598698**Result** ✓ Passed**MOT #9** 2017-10-06 08:47**MOT test number** 922799433741**Result** ✓ Passed**MOT #8** 2016-08-24 09:00**MOT test number** 962757993616**Result** ✓ Passed**MOT #7** 2015-12-17 11:28**MOT test number** 709416230617**Result** ✓ Passed**MOT #6** 2015-01-08 10:02**MOT test number** 458288705098**Result** ✓ Passed**MOT #5** 2014-01-07 14:27**MOT test number** 456007904029**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-01-07 09:36**MOT test number** 807267303035**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2012-01-10 10:10
MOT test number	635810712041
Result	✓ Passed
MOT #2	2011-01-21 11:42
MOT test number	439671421089
Result	✓ Passed
MOT #1	2010-01-15 13:40
MOT test number	282985810098
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
6 August 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	6 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-29
Last registration	2023-08-07
Complete history	<a href="#">See info</a>



Registration #1	2007-01-29	17 mi
Registration #2	2010-01-15	22.575 mi
Registration #3	2011-01-21	29.100 mi
Registration #4	2012-01-10	31.409 mi
Registration #5	2013-01-07	34.560 mi
Registration #6	2014-01-07	38.268 mi
Registration #7	2015-01-08	41.389 mi
Registration #8	2015-12-17	45.077 mi
Registration #9	2016-08-24	47.969 mi
Registration #10	2017-10-06	53.356 mi
Registration #11	2018-01-29	55.377 mi
Registration #12	2018-05-29	57.377 mi
Registration #13	2018-09-29	59.377 mi
Registration #14	2019-01-29	61.377 mi
Registration #15	2019-05-29	63.377 mi
Registration #16	2019-09-29	65.377 mi
Registration #17	2020-01-29	67.377 mi
Registration #18	2020-05-29	69.377 mi
Registration #19	2020-09-29	71.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKS 044415