



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	AGILA S AC ECOFLEX
Colour	Green
Year of manufacture	2011
Top speed	99 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	64 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2

Date	2021-07-01
Pictures	20
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-06-21
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-06-26
<b>MOT pass rate</b>	79 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	18
<b>Total items failed</b>	4

**MOT #14** 2023-06-27 08:08**MOT test number** 561143355470**Result** Passed**Next expiry date** 2024-06-26

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2022-06-20 10:31**MOT test number** 961480656742**Result** Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #12** 2022-06-20 10:31**MOT test number** 548979093963**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #11** 2021-06-21 11:50**MOT test number** 460837175979**Result** ✓ Passed**MOT #10** 2020-08-12 07:35**MOT test number** 733373219653**Result** ✓ Passed**MOT #9** 2019-09-06 09:10**MOT test number** 136633596192**Result** ✓ Passed**MOT #8** 2019-06-04 13:39**MOT test number** 929795576597**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2019-06-04 09:41**MOT test number** 640730242389**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2018-06-13 08:07**MOT test number** 610186845863**Result** ✓ Passed**Advice** Intermittent poor flow on washer jets**Minor** Front Windscreen wiper blade defective starting to smear (3.4 (b) (i))**MOT #5** 2017-06-14 10:11**MOT test number** 118065614525**Result** ✓ Passed**Advice** N/s/f and o/s/f wiper blades starting to smear windscreen**Advice** Unable to see front outer brake pads (wheel trims fitted)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** N/s/r and o/s/r tyres starting to perish inside tread**MOT #4** 2016-05-23 13:16**MOT test number** 161974985754**Result** ✓ Passed**MOT #3** 2016-05-23 13:16**MOT test number** 279723358712**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)



MOT #2	2015-06-15 10:17
MOT test number	206556565143
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

MOT #1	2014-06-04 14:58
MOT test number	318095654199
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
26 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	64
<b>MOT expiry date</b>	26 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>VAUXH</b>
Plate since	2024-03-29
Current registration	 <b>VAUXH</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-06-20
Last registration	2023-06-27
Complete history	<a href="#">See info</a>



Registration #1	2011-06-20	14 mi
Registration #2	2014-06-04	26.910 mi
Registration #3	2015-06-15	34.560 mi
Registration #4	2016-05-23	38.938 mi
Registration #5	2016-05-23	38.938 mi
Registration #6	2017-06-14	45.305 mi
Registration #7	2018-06-13	53.737 mi
Registration #8	2019-06-04	60.799 mi
Registration #9	2019-06-04	60.799 mi
Registration #10	2019-06-04	60.799 mi
Registration #11	2019-06-04	60.799 mi
Registration #12	2019-06-04	60.799 mi
Registration #13	2019-06-04	60.799 mi
Registration #14	2019-06-04	60.799 mi
Registration #15	2019-06-04	60.799 mi
Registration #16	2019-06-04	60.799 mi
Registration #17	2019-06-04	60.799 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	985 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1094137