



report date: 2024-03-28

General information

Make	NISSAN
Model	PIXO VISIA
Colour	Grey
Year of manufacture	2011
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-27
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-06
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	26
Total items failed	6

MOT #15	2024-03-15 08:59
MOT test number	677414854842
Result	✓ Passed
Next expiry date	2025-04-06

MOT #14	2023-03-27 13:38
MOT test number	367740664490
Result	✓ Passed

MOT #13	2022-04-07 08:34
MOT test number	458613714627
Result	✓ Passed

MOT #12	2021-03-17 18:14
MOT test number	545964840591
Result	✓ Passed
Minor	Offside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Position lamp cracked but no white light showing

**MOT #11**

2021-03-17 17:25

MOT test number

708035815287

Result**✗ Failed****Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Offside Rear Position lamp cracked but no white light showing

Minor

Offside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10

2020-04-01 11:23

MOT test number

300898058892

Result**✓ Passed****Advice**

Nearside Front Inner Drive shaft joint constant velocity boot slightly leaking.

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge 2 mm (5.2.3 (e))

Advice

Offside Rear Light cluster lens damaged

Advice

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

2019-04-02 13:03

MOT test number

126126382054

Result**✓ Passed****Advice**

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2019-04-02 10:09**MOT test number** 892853148767**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2018-03-30 16:05**MOT test number** 545918465616**Result** ✓ Passed**Advice** Offside Front Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front both inner driveshaft gaiters show slight traces of grease from clips**MOT #6** 2018-03-30 16:05**MOT test number** 231930426783**Result** ✗ Failed**Advice** Front both inner driveshaft gaiters show slight traces of grease from clips**Advice** Offside Front Outer Road wheel with a slightly distorted bead rim (4.2.A.1a)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)**MOT #5** 2017-03-29 15:15**MOT test number** 840258013076**Result** ✓ Passed**Advice** Oil level considerably overfull**Advice** Front brake disc worn, pitted or scored, but not seriously weakened s (3.5.1i)

**MOT #4** 2017-03-29 15:15**MOT test number** 319544590013**Result** ✗ Failed**Pass with rectification** Offside Front Wheel nut(s) loose (4.2.A.1e)**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Oil level considerably overfull**Advice** Front brake disc worn, pitted or scored, but not seriously weakened s (3.5.1i)**MOT #3** 2016-04-01 10:04**MOT test number** 557405840345**Result** ✓ Passed**Advice** Nearside Front SLIGHT CUT IN TYRE OUTER SIDE WALL**MOT #2** 2015-04-02 10:10**MOT test number** 605542295028**Result** ✓ Passed**Notice** N/s/r tyre wearing on outer edge**Notice** N/s wiper split at ends**MOT #1** 2014-03-27 09:53**MOT test number** 748566684079**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	6 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-06-20
Current registration	
Plate since	2019-06-20

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-30
Last registration	2024-03-15
Complete history	See info



Registration #1	2011-03-30	13 mi
Registration #2	2014-03-27	14.832 mi
Registration #3	2015-04-02	19.604 mi
Registration #4	2016-04-01	23.895 mi
Registration #5	2017-03-29	28.898 mi
Registration #6	2017-03-29	28.898 mi
Registration #7	2018-03-30	34.838 mi
Registration #8	2018-03-30	34.838 mi
Registration #9	2019-04-02	41.700 mi
Registration #10	2019-04-02	41.700 mi
Registration #11	2019-04-02	41.700 mi
Registration #12	2019-04-02	41.700 mi
Registration #13	2019-04-02	41.700 mi
Registration #14	2019-04-02	41.700 mi
Registration #15	2019-04-02	41.700 mi
Registration #16	2019-04-02	41.700 mi
Registration #17	2019-04-02	41.700 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	133813