



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR
Colour	Silver
Year of manufacture	2003
Top speed	149 mph
0 - 60 mph	7.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-01
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-04-12
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	45
Total items failed	8

MOT #23	2023-04-13 13:14
MOT test number	613155579936
Result	✓ Passed
Next expiry date	2024-04-12
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Rear Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))

MOT #22	2022-01-24 14:51
MOT test number	606909925707
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Front Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Suspension component corroded but not seriously weakened both sides (5.3.3 (b) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #21**

2022-01-10 13:22

**MOT test number**

657665055650

**Result****✗ Failed**

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Suspension component corroded but not seriously weakened both sides (5.3.3 (b) (i))

**MOT #20**

2021-01-05 12:43

**MOT test number**

952398056548

**Result****✓ Passed**

- Advice** Front Tyre worn close to legal limit/worn on edge o/s and n/s (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake pipe corroded, covered in grease or other material o/s and n/s (1.1.11 (c))

**MOT #19**

2020-01-06 15:57

**MOT test number**

178659704643

**Result**

✓ Passed

**Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive both sides (5.3.6 (a) (i))**Advice** Under trays loose**MOT #18**

2020-01-02 12:56

**MOT test number**

326565122408

**Result**

✗ Failed

**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive both sides (5.3.6 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Under trays loose**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #17**

2019-01-05 10:05

**MOT test number**

547263212141

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Undertrays fitted**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material all steel (1.1.11 (c))

**MOT #16** 2017-07-28 09:34**MOT test number** 796025395136**Result** ✓ Passed**MOT #15** 2016-08-01 11:04**MOT test number** 303782170124**Result** ✓ Passed**MOT #14** 2016-01-08 10:59**MOT test number** 194850029082**Result** ✓ Passed**Advice** Slight play in steering box**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #13** 2015-01-09 16:14**MOT test number** 588739205087**Result** ✓ Passed**MOT #12** 2015-01-09 12:25**MOT test number** 165179505081**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicators not working (1.4.A.2c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2014-01-23 11:59**MOT test number** 967083724004**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

**MOT #10** 2013-01-22 12:36**MOT test number** 606612523054**Result** ✓ Passed**MOT #9** 2012-01-23 14:09**MOT test number** 139303322464**Result** ✓ Passed

- Notice** Noise heard on steering

**MOT #8** 2012-01-23 14:09**MOT test number** 887653822069**Result** ✗ Failed

- Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Notice** Noise heard on steering

**MOT #7** 2011-01-19 15:41**MOT test number** 196019311421**Result** ✓ Passed



<b>MOT #6</b>	2011-01-19 10:52
---------------	------------------

<b>MOT test number</b>	268019811057
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

<b>Fail</b>	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--

<b>MOT #5</b>	2010-01-20 11:09
---------------	------------------

<b>MOT test number</b>	213530620057
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2009-01-23 10:12
---------------	------------------

<b>MOT test number</b>	910773229037
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2008-01-16 15:19
---------------	------------------

<b>MOT test number</b>	174356918419
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2007-01-08 10:59
---------------	------------------

<b>MOT test number</b>	783118007056
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2006-01-27 10:57
---------------	------------------

<b>MOT test number</b>	124257826425
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------





Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✗  
**MOT**  
  
Expired:  
12 April 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	12 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-03-21
Last registration	2023-04-13
Complete history	<a href="#">See info</a>



Registration #1	2003-03-21	24 mi
Registration #2	2006-01-27	27.272 mi
Registration #3	2007-01-08	34.373 mi
Registration #4	2008-01-16	40.456 mi
Registration #5	2009-01-23	46.786 mi
Registration #6	2010-01-20	53.442 mi
Registration #7	2011-01-19	59.312 mi
Registration #8	2011-01-19	59.312 mi
Registration #9	2012-01-23	65.974 mi
Registration #10	2013-01-22	71.783 mi
Registration #11	2014-01-23	77.694 mi
Registration #12	2015-01-09	83.531 mi
Registration #13	2015-01-09	83.531 mi
Registration #14	2015-01-09	83.531 mi
Registration #15	2015-01-09	83.531 mi
Registration #16	2015-01-09	83.531 mi
Registration #17	2015-01-09	83.531 mi
Registration #18	2015-01-09	83.531 mi
Registration #19	2015-01-09	83.531 mi
Registration #20	2015-01-09	83.531 mi
Registration #21	2015-01-09	83.531 mi
Registration #22	2015-01-09	83.531 mi
Registration #23	2015-01-09	83.531 mi
Registration #24	2015-01-09	83.531 mi

More info >



Dimensions & weight

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	1198332476492